



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District I/3district.htm](http://emnr.state.nm.us/ocd/District%20I/3district.htm)

GARY E. JOHNSON  
Governor

Jennifer A. Salisbury  
Cabinet Secretary

March 31, 1999

John C. Corbett  
Northstar Oil & Gas Corp.  
P.O. Box 93  
Farmington, NM 87499

RE: DAVIE #1 M-02-29N-15W API 30-045-25092

Dear Mr. Corbett:

Our records indicate that the well listed above is inactive and not in compliance with Rule #201.B.

Please submit plans to bring this well into compliance within 30 days. Review Rules #202 and #203 for the necessary filing requirements to plug and abandon or temporarily abandon this well.

Feel free to call me at 334-6178, ext 12, if I can be of any help.

Sincerely,

Bruce Martin  
Deputy O&G Inspector

XC: BM File  
Well File

*Case 13920  
Northstar Oil & Gas  
OCD Exhibit No. 5*



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emrdd.state.nm.us/ocd/District III/District.htm](http://emrdd.state.nm.us/ocd/District%20III/District.htm)

GARY E. JOHNSON  
Governor

Jennifer A. Salisbury  
Cabinet Secretary

March 31, 1999

John C. Corbett  
Northstar Oil & Gas Corp.  
P.O. Box 93  
Farmington, NM 87499

RE: **BARBARA #1 P-12-29N-15W API 30-045-24263**

Dear Mr. Corbett:

Our records indicate that the well listed above is inactive and not in compliance with Rule #201.B.

Please submit plans to bring this well into compliance within 30 days. Review Rules #202 and #203 for the necessary filing requirements to plug and abandon or temporarily abandon this well .

Feel free to call me at 334-6178, ext 12, if I can be of any help.

Sincerely,

Bruce Martin  
Deputy O&G Inspector

XC: BM File  
Well File

*Case 13920  
Northstar Oil & Gas  
OCD Exhibit No. 6*

Submit 3 Copies  
To Appropriate  
District Office  
DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
811 South First, Artesia NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico  
Energy, Minerals and Natural Resources Department

**OIL CONSERVATION DIVISION**

2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised 1-1-89

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. 30-045-24263
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Northstar Oil and Gas Corp		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 93 Farmington, NM 87499		7. Lease Name or Unit Agreement Name: Barbara
4. Well Location Unit letter <u>(P)</u> : 760 feet from the <u>South</u> line and <u>810</u> feet from the <u>East</u> line Section <u>12</u> Township <u>29N</u> Range <u>15W</u> NMPM San Juan County		8. Well No. <u>1</u>
I. Elevation (Show whether DF, RKB, RT, GR, etc.) 5179 G.L.		9. Pool name or Wildcat Cha Cha Gallup

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

**NOTICE OF INTENTION TO:**

**SUBSEQUENT REPORT OF:**

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
PULL OR ALTER CASING ☐ CASING TEST AND CEMENT JOB ☐  
OTHER: ☐ OTHER: ☐

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

1. Check anchors and prepare location
  2. R.U. workover rig. Kill well if necessary. Nipple up wellhead and BOP.
  3. Pull and inspect existing tubing.
  4. RIH with tubing and packer.
  5. Test casing and acidize Gallup perforations.
  6. Pull packer and re-run tubing with seat nipple.
  7. Drop bumper sub and plunger and hang on to test potential Gallup production.
- Operations are expected to begin within 90 days, but depend on negotiations with landowners.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John C. Corbett TITLE President DATE 5/14/1999  
Type or print name John C. Corbett Telephone No. (505) 327-5751

(This space for State use)

APPROVED BY ORIGINAL SIGNED BY CHARLIE T. PERREN

TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE MAY 14 1999

Conditions of approval, if any:

Case 13920  
Northstar Oil & Gas  
OCD Exhibit No. 7