

19.15.4.201 WELLS TO BE PROPERLY ABANDONED:

A. The operator of any of the following wells, whether cased or uncased, shall be responsible for the plugging thereof: wells drilled for oil or gas; or service wells including but not limited to seismic, core, exploration or injection wells.

B. A well shall be either properly plugged and abandoned or placed in approved temporary abandonment in accordance with these rules within 90 days after:

- (1) a 60 day period following suspension of drilling operations;
- (2) a determination that a well is no longer usable for beneficial purposes; or
- (3) a period of one year in which a well has been continuously inactive.

[7-12-90...2-1-96; 19.15.4.201 NMAC - Rn, 19 NMAC 15.D.201. 12-14-01; A, 12/15/05]

Tom R. Cone

***Case 14076
OCD Exhibit No. 4***