Subj:

FW: State R

Date:

2/13/2008 8:01:31 A.M. Central Standard Time

From:

bmartin@mtienergy.com

To: CC: kevnbutir@aol.com ccopeland@mtienergy.com, smadry@geedmidland.com, geed-acct@geedmidland.com

Kevin,

As you know from our visit to the State R yesterday the 3" valve on the back of the tank had not been replaced and there were no signs of leaking. The only clean up that had been done was out side the location where it was obvious multiple trucks had been turning around. If the OCD took pictures I am sure they will come to their own conclusions. Also I so no signs of the old circulating pump leaking at all. Based on the water production numbers and the size of the tank I have no doubt that the new circulating pump could have been installed in time to have prevented water hauling by truck. I will be talking with Louis on a few of the notes that I took yesterday. However I will not push this issue until we have plans made. The note below does not fit with the evidence and appears to be a weak attempt to devert the blame. At this point I certainly do not have a good feeling about the integrity of Louis. The obvious fact that Louis is not taking care of the wells as he should is also troubling. The heater treater on the State 32 was a good example.

Thanks, Bruce.

From: Louis G. Edgett [mailto:louray@valornet.com]

Sent: Mon 2/11/2008 10:24 PM To: Greg Lopez; Bruce Martin

Subject: State R

**

Bruce, On 2/8/2008 An Energen pumper Rex Smith called me and started telling me I was a sorry Sob. He said we were unloading water in the St. R lease. I could not get a word in to tell him what we doing. I called the truck to tell him to leave, because the Energen pumper was on Butlers lease threatening the driver. We were going to empty the tank and change the 3" valve on the back because it was leaking. When the Transfer pump started leaking I had the water hauled off so I would not have to shut the lease down. The St. R will not make up the lost Production. The Energen Pumper also said that Kevin was a crook and that he was going to call the OCD on him for the leak on the pump and tank. I called a back hoe and sent him to the St. R to pick up the contaminated dirt and clean up. The OCD showed up while the backhoe was there and took pictures.

This email has been scanned by the MessageLabs Email Security System. For more information please visit http://www.messagelabs.com/email

This email has been scanned by the MessageLabs Email Security System. For more information please visit http://www.messagelabs.com/email