1	
	7
	\$1
	7
	B
	BUR
	~
	0

PRODUCTIO LOG

ompany ENRON OIL	ENRON OIL AND GAS COMPANY				
	JAMES RANCH UNIT NO.71				
ield LOS MEDANO	LOS MEDANOS BONE SPRING DELAWA	ELAWA			
ounty EDDY	E MECTOO		Country Hop		
Number	30-015-27927	Filing	1	W941310	
NL A	D 660' FEL			Other T-CHEK	r Services EK
SD: SEC:	36 TWP:	22-S RGE:	30-E		
0 0	Ø min.	sec.			
ongitude: Ø deg.	Ø min.	Sec. W			
60	-	33		XB:	3338.70 F
		10.70	HOOVE T.D.	<u>ַ</u>	3333 99 5
rilling Measured from	Om K.B.			CBF:	.00 F
ate	12/07/94				
un Number	1	2	3		4
ob Ticket Number	671464-2				
131	11170.00 F				
ast Recorded Depth	10765.00 F				
	11184.00 F				
ottom Depth Drille	711204.00 F				
asing size					
asing shoe Driller				-	
1 tsize	7.875			-	
	NA			-	
ource of sample	NA			-	
luid Density				-	
luid Viscosity					
ud pH					
n @ Meas. Temp.	8	B	9		a
nc @ Meas. Temp.	a	9	9		9
	9	9	9		e
@ BHT	e 163	9	9		e
ource Rmf	NA				
ource Rmc	NA				
ax. Recorded Temp.	163				
ime End Circulatio	HR	H		퓨	HR
ime logger at TD	13:30 HR	I		퓨	HR
quipment number	50641	50641	50641	56	50641
quipment location	ODESSA, TEXAS				
ecorded by	RHO				
tnessed by	MR. R. SHOTTZ				
		The same of the sa	State of State Sta		The same of the last of the la

REMARKS:	PRODUCTION	1	PERCENTAGES-TOP	ZONE	1	! PERCENTAGES-BOTTOM ZONE
	Gas	1	95% - 100%		1	1 0% - 5%
	0 i 1	1	10% - 20%		1	1 80% - 90%
	Water	1	10% - 20%		1	1 80%- 90%

HALLIBURTON does not guarantee the accuracy of any interpretation of log data, conversion of log data to physical rock parameters, or recommendations which may be given by Halliburton personnel or which may appear on the log or in any other form. Any user of such data, interpretations, conversions, or recommendations agrees that Halliburton is not responsible, except where due to gross negligence or willful misconduct, for any loss, damages, or expenses resulting thereof.

HALLIBURTON