

GENERAL OFFICES
120 BROADWAY NEW YORK

AMERADA PETROLEUM CORPORATION

BEACON BUILDING
P. O. BOX 2040
TULSA 2, OKLA.

March 23, 1955

Oil Conservation Commission of New Mexico
P.O. Box 871
Santa Fe, New Mexico

Attention: Mr. W. B. Macey, Secretary-Director

Gentlemen:

We have received copies of Order No. R-592 and Order No. R-597. We wish to point out several errors, to-wit:

In Order No. R-592, Paragraph (4) on Page 2, the designated well should be Weir Well No. 4 and not Well No. 1.

In Paragraph (2) under "It Is Therefore Ordered," the designated well should be Weir No. 4 and not Weir No. 1.

In Order No. R-597, Paragraph (2) under "It Is Therefore Ordered," Weir No. 4 is located in the SE/4 of the NW/4 and not in the SW/4 of the NW/4 of Section 35.

This is called to your attention so that you may correct your copies, or if you prefer, you may send us copies of new originals if new originals are to be made.

For your convenience, we are attaching a plat of the unit.

Yours very truly,

R. S. Christie
R. S. Christie

RSC:mt
attachment

OIL CONSERVATION COMMISSION

P. O. BOX 871

SANTA FE, NEW MEXICO

March 11, 1955

Amerada Petroleum Corporation
Box 2040
TULSA, OKLAHOMA

Attention: Mr. R. S. Christie

Gentlemen:

We attach copies of Orders R-592 and R-597 issued in Cases 827 and 796, which were heard by this Commission under date of February 28, 1955.

Very truly yours,

W. B. Macey
Secretary - Director

WBM:nr

C
O
P
Y