

475 operating costs


75% Kimball
25% Campbell Est

33,000 Kimball cost
11,000 Campbell cost

670
122
182
1200
185
81.5
R-6W

Proposed unit

PB from DK was not a good producer in T-25N



150% value

avg delay 864/day on plat
mean delay 568/day " "

6-7 yrs to pay out w/ out well? 864 delay.

BEFORE EXAMINER NUTTER
OIL CONSERVATION COMMISSION
App EXHIBIT NO. One
CASE NO. 2574

Exhibit No. 1
Acreage + Well Plat
Vicinity of W/2, Sec. 35
T-25N, R-6W, Rio Arriba Co, N.M.
Showing Dakota Wells Only.