

FRESH WATER WELLS IN T-20S, R-38E IN THE WARREN UNIT AREA,
AS REPORTED BY MR. DON URBINA, STATE ENGINEER, ROSWELL OFFICE

INFORMATION FURNISHED BY MR. URBINA

RESULTS OF FIELD SEARCH

- | | |
|---|--|
| 1. Sec. 24 - NW4/NW4/NW4 - Stock Well
Owner: Dallas McCasland
Drilled: 12/13/88
T.D.: 53'
Water Level: 30' (as reported by driller)
Casing: 5" PVC | This stock well was located and a water sample secured for analysis. |
| 2. Sec. 24 - SW4/SW4/SW4/NW4/NW4 - Stock Well
Owner: Dallas McCasland
Drilled: 12/29/88
T.D.: 58'
Casing: 4 1/2" PVC | This is not an active well. Only a 4 1/2" PVC pipe inside a 5 1/2" metal riser were found at the surface at this location. |
| 3. Sec. 26 - SE4/SW4 - Domestic Well
Owner: Millard Deck
Drilled: 6/5/78
T.D.: 130'
Water Level: 65'
Casing: 6 5/8" | No remaining surface evidence of this well was found. |
| 4. Sec. 34 - SW4/SW4/NE4 - Stock Well
Owner: E. C. Hill
Drilled: 2/10/81
Water Level: 78.34' (as reported by state)
Casing: 4" | This stock well was located and a water sample secured for analysis. |
| 5. Sec. 34 - SW4/SW4/NE4 - Stock Well
Owner: E. C. Hill
Drilled: 2/18/86
Water Level: 79.12' (as reported by state) | No remaining surface evidence of this well was found. |

BEFORE EXAMINER STOGNER OIL CONSERVATION DIVISION
EXHIBIT NO. <u>21</u>
CASE NO. <u>10220</u>
Submitted by <u>Conoco Inc.</u>
Hearing Date <u>1-24-91</u>