Submit 1 Copy To Appropriate District	State of New Mex	V100	MNRD-OCD ARTESIA Form C-103
Office	Energy, Minerals and Natur	R	EC'D: 7/27/2020 Form C-103 Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Difference and I taken	tui Resources	WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-015-22006
District III - (505) 334-6178	1220 South St. Fran		5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87	505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			STATE 21 COM
PROPOSALS.)			
1. Type of Well: Oil Well Gas Well Other		8. Well Number #001	
2. Name of Operator OXY USA WTP LP		9. OGRID Number 192463	
3. Address of Operator		10. Pool name or Wildcat	
PO BOX 4294, HOUSTON, TX 77210 4. Well Location		SALADAR STRAWN/BF WOLFCAMP	
Unit Letter B: 660 feet from the NORTH line and 1980 feet from the EAST line			
Section 21		nge 28E	NMPM County EDDY
Section 2.	11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Charle Ammanuista Dan to Indicate Nature of Nation Demont on Other Date			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN	DE CONTROL CON		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM			П
OTHER: ADD PERFS IN WOLFCAMP 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
OXY respectfully requests to close strawn perforations, perforate and produce the wolfcamp formation. See attached previously submitted recompletion permit approved on 11/19/2018.			
previously submitted recompletion permit approved on 11/19/2016.			
Plan Forward:			
MIRU. Unset packer and POOH with tubing. Clean out to 11000'. RIH and set CIBP @ 10964', dump bail 35' cement to 10929'.			
Perf from 9125' - 9135', 9140' - 9146', 9150' - 9155', 9166' - 9183' and stimulate.			
Flowback and turn to production.			
Morrow perfs - 11064 - 11164			
Strawn proposed? perfs - 10140 - 10160			
Spud Date:	Rig Release Dat	te:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Thereby certify that the information above is true and complete to the best of my knowledge and bench.			
SIGNATURE WILL TITLE REGULATORY ADVISOR DATE 2/17/20			
3			
Type or print name LESLIE REE	E-mail address:	LESLIE_REEVE	S@OXY.COM PHONE: 713-497-2492
For State Use Only			
APPROVED BY:	DENIED		DATE_ gc 7/30/2020
Conditions of Approval (if any):			