

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-41986
5. Indicate Type of Lease STATE [X] FEE []
6. State Oil & Gas Lease No. 36900
7. Lease Name or Unit Agreement Name RDX 16
8. Well Number 025
9. OGRID Number 246289
10. Pool name or Wildcat BRUSHY DRAW; DELAWARE, EAST
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,083'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [X] Gas Well [] Other []
2. Name of Operator WPX Energy Permian, LLC
3. Address of Operator 3500 ONE WILLIAMS CENTER MD 35 TULSA, OK 74172
4. Well Location Unit Letter J : 1650 feet from the SOUTH line and 1790 feet from the EAST line
Section 16 Township 26S Range 30E NMPM EDDY County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,083'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
DOWNHOLE COMMINGLE []
CLOSED-LOOP SYSTEM []
OTHER: []
SUBSEQUENT REPORT OF:
REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS. [] P AND A [X]
CASING/CEMENT JOB []

Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.emnrd.state.nm.us

13. Describe proposed or completed operations. (Clearly state all parts of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

08/31/20 MIRU plugging equipment. Bled well down. POH w/ rods and pump.
09/01/20 ND WH, NU BOP. POH w. tbg and TAC. RIH and set 5 1/2 CIBP @ 5680. Circ. Hole w/ MLF. Pressure up to 600 psi. Held. Spotted 25 sx class C @ 5680-5433.
09/02/20 Tag plug @ 5480. Perf'd csg @ 3531. Pressured up 600 psi. Spotted 30 sx class C @ 3581-3278.
09/03/20 Tag plug @ 3310. Spotted 25 sx class C @ 2600-2353. Perf'd & Sqz'd 50 sx class C @ 820-620. WOC. Tagged plug @ 565. Perf'd & Sqz'd 70 sx class C @ 200-surface.
09/04/20 ND WH. Verified cement at surface. RDMO.
09/09/20 Moved in welder and backhoe. Dug out wellhead and anchors. Cut off wellhead. Welded on "Above Ground Dry Hole Marker". Cleaned location and moved off.

Spud Date: 02/16/2014

Rig Release Date: 03/03/2014

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Caitlin O'Hair TITLE Regulatory Specialist DATE 09/10/2020

Type or print name Caitlin O'Hair E-mail address: caitlin.ohair@wpxenergy.com PHONE: 539-573-3527

For State Use Only

APPROVED BY: [Signature] TITLE Staff Manager DATE 9/11/2020
Conditions of Approval (if any):