Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OH, GONGERNA TION BRIGGON	WELL API NO. 30-015-47278
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE X
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505	TOTAL AND DEPONDED ON MARK A	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Beagle 35-34-22-27 Fee
1. Type of Well: Oil Well Gas Well X Other		8. Well Number 402H
2 Name of Operator	rgy Permian, LLC	9. OGRID Number 246289
		10. Pool name or Wildcat
3500 One William	ns Center, Tulsa, OK 74172	Purple Sage; Wolcamp (Gas)
4. Well Location		
Unit Letter P : 1076 feet from the South line and 638 feet from the East line		
Section 35	Township 22S Range 27E	NMPM County Eddy
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
12 Chack Appropriate Roy to Indicate Nature of Notice Report or Other Data		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ADAMS CASING REMEDIAL WORK ADAMS CASING REMEDIAL WORK REMEDIA		
TEMPORARILY ABANDON		
DOWNHOLE COMMINGLE	-	
CLOSED-LOOP SYSTEM		_
OTHER:	Distributions (Clearly state all partiagnt datails, or	d give portinent dates including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
Once we finished our logging and coring operation of the pilot hole, we tripped in the hole with 2-7/8" tubing and pumped a		
cement plug from 8408' to 8983'. After 3 failed attempts to kick off from the cement plug in the pilot hole, we opted to go with a		
hydraulic openhole whipstock. While running the whipstock in the hole, it became stuck at 6593' (bottom of whipstock slide at 6572'). The decision was made to set the whipstock at this depth due to the potential of shearing off from the tool if we attempted		
to slack off or pick up too much weight on the assembly. After confirming the orientation of the whipstock slide, we set the		
whipstock and sheared off the mills to drill the window. This window was drilled successfully. We tripped out for our 8-3/4"		
assembly and proceeded to drill down to kick off point with no further issues.		
	OCD Accepted for Record 11/5/2020 - JAC	6
G 1D (n: n l n n	
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE DOWN THE	TITLE Regulatory Technician	DATE_10/22/2020
,		
Type or print name Dana Thompson E-mail address: dana.thompson@wpxenergy.compHONE: 539-573-3588		
For State Use Only		
APPROVED BY:	TITLE	DATE
Conditions of Approval (if any):		