

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG-5582	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator		
The Desana Corporation		
Address of Operator		
600 Bldg of the Southwest, Midland, Texas 79701		
Location of Well		
UNIT LETTER	M	660 FEET FROM THE West LINE AND 660 FEET FROM
THE south LINE, SECTION	36	TOWNSHIP 5-N RANGE 30-E NMPM.

7. Unit Agreement Name
8. Farm or Lease Name
Wichita-State
9. Well No.
1
10. Field and Pool, or Wildcat
Wildcat

15. Elevation (Show whether DF, RT, GR, etc.)
4602.1 GL

12. County
Quay

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASINGS <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

4-20-86 Circ hole w/10.0 ppg salt gel mud. Set CIBP @ 2050'. Cap w/30' cmt (2sx). Shot csg @ 1600' - will not work free. Shot csg @ 1500' - would not work free. Shot csg. @ 1000'. Pulled csg. Ran tbg to 1050'. Spotted 80sx cmt. @ 1050' (Inside 4-1/2" csg. & up in 8-5/8" csg.). Spotted 15sx cmt plug from 60' to surface.

Note: All cmt plugs are Class "C" mixed @ 14.6 ppg.
4-22-86 Weld on plate & Installed dry hole marker. Well P & A 4-22-86.
Covered up pits and cleaned up location.

Location is ready for inspection.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED K. V. Tholstrom TITLE Operations Manager DATE May 27, 1986

APPROVED BY K. V. Tholstrom TITLE DISTRICT SUPERVISOR DATE 10-31-86

CONDITIONS OF APPROVAL, IF ANY: