DISTRIBUTION  SANTA FE  FILE  U.S.G.S.  LAND OFFICE  OPERATOR	NEW MEXICO OIL CONSERVATION COMMISSION	Supersedes Old C-102 and C-103
U.S.G.S.  LAND OFFICE	NEW MEXICO OIL CONSERVATION COMMISSION	
J.S.G.S.		Effective 1-1-65
AND OFFICE	i e	<u></u>
		Sa. Indicate Type of Lease
OPERATOR		State Fee.
		5. State Oil & Gas Lease No.
	<del>-</del>	***
	RY NOTICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. RITION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL	OTHER-	7. Unit Agreement Name
D. W. St. Clair		8. Farm or Lease Name  Sedberry
, Address of Operator		9. Well No.
501 Pirst Nati	ional Bank Bldg., Midland, Texas 79701	1
. Location of Well		10. Field and Pool, or Wildcat
UNIT ELITTER	990 FEET FROM THE SOUTH LINE AND 660 FEE	Wildcat Wildcat
•	THE AND	VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
THE East LINE SECT	ton 25 township 17N RANGE 16 E	NMPM.
LINE, SECT	TOWNSHIP RANGE	
	15. Elevation (Show whether DF, RT, CR, etc.)	12. County
	6630 Est.	San Miguel
Cheels	Appropriate Box To Indicate Nature of Notice, Report	or Other Data
	· · · · · · · · · · · · · · · · · · ·	UENT REPORT OF:
NOTICE OF I	SUBSEC	GENT REPORT OF:
OF OF ONLY BELIEF WORK	5/1/5 4/12 4/12 4/12 5/1/5/1/   -5/1/5/1/ Wast	¬
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	<u></u>
	OTHER	
OTHER		
17. Casaribe Proposed or Completed C	perations (Clearly state all pertinent details, and give pertinent dates, inc	<del></del>
		cluding estimated date of starting any proposed
	g up Lohmann Well Service, Inc. rig. 100' - : on 12 3/4" casing w/500#, held 30 minutes o	12 3/4" Set @ 108' w/100 sa
		12 3/4" Set @ 108' w/100 sap o.k.
		12 3/4" Set @ 108' w/100 sat o.k.
		12 3/4" Set @ 108' w/100 sat o.k.
		12 3/4" Set @ 108' w/100 sat o.k.
		12 3/4" Set @ 108' w/100 sat o.k.
		12 3/4" Set @ 108' w/100 sat o.k.
		12 3/4" Set @ 108' w/100 sat o.k.
		12 3/4" Set @ 108' w/100 sat o.k.
Pressure up	on 12 3/4" casing w/500#, held 30 minutes o	12 3/4" Set @ 108' w/100 sat o.k.
Pressure up		12 3/4" Set @ 108' w/100 sat o.k.
Pressure up	on 12 3/4" casing w/500#, held 30 minutes o	12 3/4" Set @ 108' w/100 sature.  AATH OFFICE W.  '67 Dec 27 Am 8
Pressure up	on 12 3/4" casing w/500#, held 30 minutes o	12 3/4" Set @ 108' w/100 sat o.k.

Deste TV

CONDITIONS OF APPROVE, IF ANY: