ENERGY AND MINERALS DEPAR	STEACHT		٠,		
as, as content of the state of	- ·	CONSERVATION	DIVISION	7.17	
DISTRIBUTION	T				Form C-103
SANTA FE	 	P. O. BOX 2088			Revised 10-1
FILE	3A	P. O. BOX 2088 NTA FE, NEW MEX	100 87501 JUL 3	37 1902	
U.S.G.S.	 	·		Sa. Indicale T	ype of Lease
LAND OFFICE				State	Fee X
OPERATOR		•	•	5. State Oil 6	Gas Lease No.
					•
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OF PLUE DATE, TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)					
1. OIL A GAS WELL WELL	OTHER-			7. Unit Agreem	ient lione
2. Name of Operator				8. Form or Lea	ise Ivame
Whigham	n Inc.			Davis-	-Pinon
3. Address of Operator				9. Well No.	
Box 199	96 Farmington,	New Mexico 87401		2	
4. Location of Well	((0	. 1		i	Pool, or Wildcat
D UNIT LETTER	660 FEET FRO	north	990 AND FE	Wildcat	· -
west	21	14N			
		TOWNSHIP RA	10E	NMPM.	
	15. Elev	ation (Show whether DF, RT,	GR, etc.)	12. County	
		6328 GR		Santa Fe	
	ck Appropriate Bo: f INTENTION TO:	x To Indicate Nature o		or Other Data QUENT REPORT OF	F:
PERFORM REMEDIAL WORK	PLU	G AND ABANDON REMEDI	IAL WORK	ALT	ERING CASING
TEMPORARILY ABANDON		COMME	NCE DRILLING OPNS.	PLUC	AND ABANDONMENT
PULL OR ALTER CASING	CHA	NGE PLANS CASING	TEST AND CEMENT JOB		-
		- OTHE	ER		L
OTHER	* *				- 17 f
17. Describe Proposed or Complete work) SEE RULE 1103.	d Operations (Clearly st	ate all pertinent details, and	give pertinent dates, in	cluding estimated date o	f starting any propos
Smart 5/16/70 Adam	. 4	11. 1150 C .			*
Spud 5/16/79. Air	. driiled 6 1/4 -+om 5/17/70 **/5	noie to libu leet	Did not run	L-log. Spotte	d 25 sx
cement plug on bot NME & MD. Dry hol	.com 5/1///9 w/3	sx in surface cast	ing as directed	by Mr. Carl Ul	vog,
NAE & AD. DIY HOL	le marker is set	and location clea	ined up, and le	veled.	w/ sen
	,				
				•	
		* *			
•			•		

16. I hereby certify that the information above is true and comple	President	DATE_	May 24, 1979
Carl Wing	DISTRICT SUPERVISOR	DATE _	7/27/82