

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		<input checked="" type="checkbox"/>
U.S.G.S.		
LAND OFFICE		
OPERATOR		

3a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
3. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WILDCAT DRY HOLE		7. Unit Agreement Name
Name of Operator COLORADO PLATEAU GEOLOGICAL SERVICES, INC.		8. Farm or Lease Name FERRILL
Address of Operator P.O. BOX 537, FARMINGTON, NEW MEXICO 87401		9. Well No. 1
Location of Well UNIT LETTER C 330 FEET FROM THE NORTH LINE AND 1650 FEET FROM THE WEST LINE, SECTION 7 TOWNSHIP 13N RANGE 9E NMPM.		10. Field and Pool, or Wildcat WILDCAT
15. Elevation (Show whether DF, RT, GR, etc.) 6010' GR		12. County SANTA FE

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In accordance with your verbal instructions we have plugged and abandoned this well by placing a 25 sack cement plug on bottom (3192') and a 25 sack plug across the bottom of the surface casing at 200'. We have also put a 10 sack plug at surface and a dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Sam C. Smith TITLE PRESIDENT CPGS DATE DEC. 8, 1981

APPROVED BY Carl Ziegler TITLE SENIOR PETROLEUM GEOLOGIST DATE 12/15/81