

3 Whigham bonds cannot be released
as of 4/17/81.

Wells : Davis-Pinon #1 & #2; both in 21-14N-10E
Santa Fe Co.

Drilled, plugged & inspected. all OK
except no C-105 forms nor logs
submitted. Operator sent notice with
copies of Rule 202 & 1105, on 4/7/80

Davis - Pueblo #1, M-35-1N-6W
Socorro Co.

Drilled & plugged but no log
submitted. We have C-105.
Operator notified & copy of Rule 202
sent.

Davis - Pueblo #2, F-35-1N-6W
Socorro Co.

Location rectored, well not drilled.

[This bond (9315333) can be
released.

Dione : No change in above, as of 7/21/81
" " " " " 12/1/81