

U.S. CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

7-10-1944
see my comments on it
Howell

C
O
P
Y

December 16, 1943

Mr. J. P. Stewart
Paducah, Texas

Re: J. P. Stewart - \$2500 - NW $\frac{1}{4}$ NE $\frac{1}{4}$ 3-3N-12E,
Torrance County. USF&G Co. 6-19-40

Dear Mr. Stewart:

For some time the scout reports reflect no activity with regard to the above captioned well - reciting that the well is in schist at 745 ft. That would seem to indicate that there would be no point in drilling further. You should, therefore, proceed to plug the well in accordance with the requirements of the Commission. You may apply to Roy Yarbrough, Oil & Gas Inspector, Hobbs, New Mexico, for a set of plugging papers and instructions regarding plugging.

I trust it will not be necessary to call upon your surety.

Very truly yours,

John M. Kelly
Director

By *Carl B. Livingston*
Chief Clerk & Legal Adviser

CBL:MS
cc Roy Yarbrough

U. S. CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

December 16, 1943

Mr. J. W. Stewart
Torrance, Texas

Mr. J. W. Stewart - \$2500 - Warrant 3-34-123
Torrance County, Texas Co. 8-19-40

Dear Mr. Stewart:

For some time the recent reports reflected no activity with regard to the above captioned well - needling that the well is in schist at 745 ft. That would seem to indicate that there would be no point in drilling further. You should, therefore, proceed to plug the well in accordance with the requirements of the Commission. You may apply to Roy Yarbrough, Oil & Gas Inspector, Hobbs, New Mexico, for a set of plugging papers and instructions regarding plugging.

I trust it will not be necessary to call upon your energy.

Very truly yours,

John H. Kelly
Director

Paul R. Livingston

Chief Clerk & Legal Advisor

cc Roy Yarbrough
Oil & Gas