

O-12-6N-7E: From above to wildcat about six miles west of Estancia reportedly slated for plugging in 1950. No well log or actual plugging report in file. Notation on C-102 (last communication received) states: "... to be plugged to satisfaction of State Engineer's Office." Check with State Engineer reveals no data on this well with that agency. Location found to be relatively well vegetated except for mound of slag and ashes. (Obviously it was a cable-tool operation.) *Chief Bell & Son Co.*

A 4 1/2" pipe extends about 2' above ground level and has a plug of some kind inside about 3' below top of pipe. Since the well was reportedly a carbon dioxide completion originally and supposedly had 6 1/4" set at 1600', the pipe now showing may be a marker stub, although no identification could be seen. There is a windmill and water tank less than 200' from this well site. Presumably the well is adequately cased and plugged or the water well would now be contaminated. Name of present landowner unknown; but reported by local residents to be a California company. Since no bond is in force, assumption is that well was properly plugged and thus file will be closed. 3/20/75 - *CU*

C-104 A		
	Operators monthly reports	
C-105	Well Log	
C-106	Request for pipe line connection	
C-107	Purchasers Monthly Report	