NEW MEXICO OIL CONSERVATION COMMISSION

SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

NOTICE OF INTENTION TO TEST CASING SHUT-OFF	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NOTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENTION TO PLUG WELL	X
OTICE OF INTENTION TO DEEPEN WELL		
11	Santa Fo N N Cart	
-	Santa Fe, N. M. Septe	enber 14,
OIL CONSERVATION COMMISSION, anta Fe, New Mexico		
fentlemen:		
following is a notice of intention to do certain work as	s described below at the	
Chief Oil & Gas Co. Pace # 1 Company or Operator Lease		
f Sec		Tricla
Torrance County.		r leiu.
FULL DETAILS OF F	PROPOSED PLAN OF WORK	
with 10 ft of top of 6 3/16. 15 sx pl well into open hole. Fill with mud to	o 530 and 15 sm plug at this point.	
with 10 ft of top of 6 3/16. 15 sx pl well into open hole. Fill with mud to From this plug to surface to be plugge Office.	to 1600. Fill with heavy mud to top lug at this point which will reach o 530 and 15 sx plug at this point. ed to satisfaction of State Engineer's	
with 10 ft of top of 6 3/16. 15 sx pl well into open hole. Fill with mud to From this plug to surface to be plugge Office.	to 1600. Fill with heavy mud to top lug at this point which will reach o 530 and 15 sx plug at this point.	
with 10 ft of top of 6 3/16. 15 sx pl well into open hole. Fill with mud to From this plug to surface to be plugge Office.	to 1600. Fill with heavy mud to top lug at this point which will reach o 530 and 15 sx plug at this point. ed to satisfaction of State Engineer's correction with large at state Engineer.	er Off.
with 10 ft of top of 6 3/16. 15 sx pl well into open hole. Fill with mud to From this plug to surface to be plugge Office.	to 1600. Fill with heavy mud to top lug at this point which will reach o 530 and 15 sx plug at this point. ed to satisfaction of State Engineer's wereaton with large at state Engineer's ell or plugging thereof."	er Off.
with 10 ft of top of 6 3/16. 15 sx pl well into open hole. Fill with mud to From this plug to surface to be plugge Office. (21/74)	to 1600. Fill with heavy mud to top lug at this point which will reach o 530 and 15 sx plug at this point. ed to satisfaction of State Engineer's recreation with large at State Engineer's ell or plugging thereof." Chief Oil & Gas Company.	er Off.