

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.	30-059-20047
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
BDCDGU 1934	
8. Well No.	011
9. Pool name or Wildcat	Tubb

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER C02	
2. Name of Operator Amoco Production Company	
3. Address of Operator PO Box 606, Clayton, NM 88415	
4. Well Location Unit Letter F : 1980 Feet From The North Line and 1976 Feet From The West Line Section 17 Township 19N Range 34E NMPM Union County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4891' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Install Casing Liner <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1934-011F  
1. MIRUSU 3/5/97  
2. NU BOP  
3. KILL WELL  
4. LAY DOWN 3 1/2 FG TBG, PKR, TAILPIPE  
5. RDMOSU 3/6/97  
6. RUN POLYBORE GAUGE RING TO 2150'  
7. RETURN WELL TO PRODUCTION 3/7/97  
8. FLOW WELL UP CSG 13 DAYS  
9. MIRUSU 3/19/97

10. RUN & SET INFL BRIDGE PLG @2140'  
11. BLEED CSG TO 0 PSI  
12. RUN 9-3 1/8 DC, FG TBG  
13. RUN POLYLINER TO 2140'  
14. RUN TOOL, 2 3/8 TBG, CATCH DC  
15. LAY DOWN TBG & DC  
16. INSTALL WELLHEAD BONNETT  
17. RDMOSU 3/22/97  
18. RETURN WELL TO PRODUCTION 3/22/97

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy E. Prichard TITLE Field Foreman DATE 3/27/97

TYPE OR PRINT NAME Billy E Prichard TELEPHONE NO. 374-3053

(This space for State Use)

APPROVED BY Ry E. Johnson TITLE DISTRICT SUPERVISOR DATE 4/18/97

CONDITIONS OF APPROVAL, IF ANY