		MEXICO UIL CONSE	RVATION COMMISSION	1	Form C-101		
SANTA FE	+	1PJ #30-059-20058				Revised 1-1-65 5A. Indicate Type of Lease	
U.S.G.S.			5A. Indicate	Type of Lease			
LAND OFFICE						Gas Lease Nu.	
OPERATOR							
						MIIIIII	
APPLICATIC	ON FOR PERMIT TO	DRILL, DEEPEN,	OR PLUG BACK		<u> </u>		
	r			_	7. Unit Agre	ement Hame	
b. Type of Well DRILL		DEEPEN	PLUG E	заск 🗌	B. Farm or L	Puso Namo	
OIL GAS WELL X			SINGLE MUL	TIPLE		rson B	
2. Name of Operator	2	·······	20NE []	ZONE	9. Well No.		
Amoco Production					1	7	
3. Address of Operator	11 1 1				10, Field an	d Pool, or Wildoat	
P. O. Box 68	Hobbs, NM 8824	1000			Und. Tubb		
4. Location of Well UNIT LETT	ER LO	CATED 1980	FEET FROM THE North	LINE	1111113	THHIHH	
7		01		с	AIIIII		
	mmminn,		т <u>wр. 19-N</u> ясе. 34-	L NMPM	12. County	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
			///////////////////////////////////////	HHHH	Union		
	iiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii	MMMMM	tttttttttt	tttttt	7777777	httilling (
<u> </u>		<u> </u>			<u>IIIIII</u>		
MMMMMMM			19. Proposed Depth 1 26001	9A. Formatio Tubb	n	20. Hutary or C.T.	
21. Elevations (Show whether DF	(<i>RT</i> , etc.) 21A. Kind	& Status Plug. Bond	21B. Drilling Contractor	Tubb	22 1	Rotary	
4828' GL		t-on-file	NA		ZZ. Approx	. Date Work will star 10–15–80	
23.					l		
		PROPOSED CASING AND	D LEMENT PROGRAM				
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF	- CEMENT	EST. TOP	
	/gr 12-1/4" 8-5/8"			+ <u> </u>			
	<u>8-5/8"</u>	24#	700'	Circ.		Surf.	
<u> </u>	<u>8-</u> 5/8" 5-1/2"	<u>24#</u> 14#	700' 2600'	Circ.		Surf.	
		14#	2600'	Circ. Tieback	to 8-5/	Surf. 8" Bottom 8-5	
Propose to drill	and equip well	14#	2600'	Circ. Tieback	to 8-5/	Surf. 8" Bottom 8-5	
Propose to drill run and evaluated	and equip well	14#	2600'	Circ. Tieback	to 8-5/	Surf. 8" Bottom 8-5	
	and equip well	14#	2600'	Circ. Tieback	to 8-5/	Surf. 8" Bottom 8-5	
Propose to drill run and evaluated production.	and equip well . Perforate an	14# in the Tubb for d stimulate as	mation. After n necessary in att	Circ. Tieback	to 8-5/	Surf. 8" Bottom 8-5	
Propose to drill run and evaluated production.	and equip well • Perforate an -700' Native m	14# in the Tubb for d stimulate as ud and fresh wa	mation. After n necessary in att	Circ. Tieback reaching tempting	TD, log	Surf. 8" Bottom 8-5 s will be ial	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700'	and equip well • Perforate an -700' Native m	14# in the Tubb for d stimulate as ud and fresh wa	mation. After n necessary in att	Circ. Tieback reaching tempting	TD, log	Surf. 8" Bottom 8-5 s will be ial	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700' BOP Attached	and equip well • Perforate an -700' Native m -TD Commercia	14# in the Tubb for d stimulate as ud and fresh wa	mation. After n necessary in att	Circ. Tieback reaching tempting	TD, log	Surf. 8" Bottom 8-5 s will be ial	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700' BOP Attached Gas is not dedica	and equip well • Perforate an -700' Native m -TD Commercia	14# in the Tubb for d stimulate as ud and fresh wa	mation. After n necessary in att	Circ. Tieback reaching tempting	TD, log	Surf. 8" Bottom 8-5 s will be ial	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700' BOP Attached Gas is not dedica	and equip well • Perforate an -700' Native m -TD Commercia	14# in the Tubb for d stimulate as ud and fresh wa	mation. After n necessary in att	Circ. Tieback reaching tempting	TD, log	Surf. 8" Bottom 8-5 s will be ial	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700' BOP Attached Gas is not dedica	and equip well • Perforate an -700' Native m -TD Commerci ted	14# in the Tubb for d stimulate as ud and fresh wa al mud with min	2600' mation. After n necessary in att ter. imum properties	Circ. Tieback reaching tempting for saf	TD, log commerc	Surf. B" Bottom 8-5 s will be ial	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700' BOP Attached Gas is not dedica	and equip well • Perforate an -700' Native m -TD Commercia	14# in the Tubb for d stimulate as ud and fresh wa al mud with min	2600' mation. After n necessary in att ter. imum properties	Circ. Tieback reaching tempting for saf for saf <i>APPR</i> Hou PER	TD, log commerc e hole co	Surf. B" Bottom 8-5 s will be ial onditions.	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700' BOP Attached Gas is not dedica	and equip well • Perforate an -700' Native m -TD Commerci ted	14# in the Tubb for d stimulate as ud and fresh wa al mud with min	mation. After n necessary in att	Circ. Tieback reaching tempting for saf for saf <i>APPR</i> Hou PER	TD, log commerc e hole co	Surf. B" Bottom 8-5 s will be ial onditions.	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700' BOP Attached Gas is not dedica	and equip well . Perforate an -700' Native m -TD Commerci ted 1-Hou 1-Sus	14# in the Tubb for d stimulate as ud and fresh wa al mud with min	2600' mation. After n necessary in att ter. imum properties 1-W. Stafford,	Circ. Tieback reaching tempting for saf for saf <i>APPR</i> Hou <i>PER</i> UN	to 8-5/ TD, log commerc e hole co VOVAL VALI MIT EXPIR LESS DRIL	Surf. B" Bottom 8-5 s will be ial onditions.	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700' BOP Attached Gas is not dedica	and equip well Perforate an -700' Native m -TD Commercia ted 1-Hou 1-Sus	14# in the Tubb for d stimulate as ud and fresh wa al mud with min	2600' mation. After n necessary in att ter. imum properties 1-W. Stafford,	Circ. Tieback reaching tempting for saf for saf <i>APPR</i> Hou <i>PER</i> UN	to 8-5/ TD, log commerc e hole co VOVAL VALI MIT EXPIR LESS DRIL	Surf. B" Bottom 8-5 s will be ial onditions.	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700' BOP Attached Gas is not dedication 0+2-NMOCD, SE	and equip well Perforate an -700' Native m -TD Commercia ted 1-Hou 1-Sus OPOSED PROGRAM: IF I EXPROGRAM: IF ANY.	14# in the Tubb for d stimulate as ud and fresh wa al mud with min sp 1-LBG	2600' mation. After n necessary in att ter. imum properties 1-W. Stafford,	Circ. Tieback reaching tempting for saf for saf <i>APPR</i> Hou <i>PER</i> UN	to 8-5/ TD, log commerc e hole co VOVAL VALI MIT EXPIR LESS DRIL	Surf. B" Bottom 8-5 s will be ial onditions.	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700' BOP Attached Gas is not dedication (0+2-NMOCD, SF) ABOVE SPACE DESCRIBE PR VE ZONE. GIVE BLOWOUT PREVENT ABOVE SPACE DESCRIBE PR VE ZONE. GIVE BLOWOUT PREVENT	and equip well Perforate an -700' Native m -TD Commercia ted 1-Hou 1-Sus OPOSED PROGRAM: IF I EXPROGRAM: IF ANY.	14# in the Tubb for d stimulate as ud and fresh wa al mud with min sp 1-LBG	2600' mation. After m necessary in att ter. imum properties 1-W. Stafford, R PLUG BACK, GIVE DATA ON powledge and bellef.	Circ. Tieback reaching tempting for saf for saf <i>APPR</i> Hou <i>PER</i> UN	to 8-5/ TD, log commerc e hole co POVAL VALI MIT EXFINIT LESS DRILL	Surf. B" Bottom 8-5 s will be ial onditions.	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700' BOP Attached Gas is not dedica 0+2-NMOCD, SE	and equip well Perforate an -700' Native m -TD Commercia ted 1-Hou 1-Sus OPOSED PROGRAM: IF I EXPROGRAM: IF ANY.	14# in the Tubb for d stimulate as ud and fresh wa al mud with min sp 1-LBG	2600' mation. After n necessary in att ter. imum properties 1-W. Stafford,	Circ. Tieback reaching tempting for saf for saf <i>APPR</i> Hou <i>PER</i> UN	to 8-5/ TD, log commerc e hole co POVAL VALI MIT EXFINIT LESS DRILL	Surf. B" Bottom 8-5 s will be ial onditions.	
Propose to drill run and evaluated production. MUD PROGRAM: 0' 700' BOP Attached Gas is not dedication (0+2-NMOCD, SF) ABOVE SPACE DESCRIBE PR VE ZONE. GIVE BLOWOUT PREVENT ABOVE SPACE DESCRIBE PR VE ZONE. GIVE BLOWOUT PREVENT	and equip well Perforate an -700' Native m -TD Commercia ted 1-Hou 1-Sus PROGRAM, IF ANY. nabove is true and comp Income	14# in the Tubb for d stimulate as ud and fresh wa al mud with min sp 1-LBG	2600' mation. After m necessary in att ter. imum properties 1-W. Stafford, R PLUG BACK, GIVE DATA ON powledge and bellef.	Circ. Tieback reaching tempting for saf for saf <i>APPR</i> Hou <i>PER</i> UN	to 8-5/ TD, log commerc e hole co POVAL VALI MIT EXFINIT LESS DRILL	Surf. B" Bottom 8-5 s will be ial onditions.	
Propose to drill run and evaluated production. MUD PROGRAM: 0' BOP Attached Gas is not dedica 0+2-NMOCD, SF	and equip well Perforate an -700' Native m -TD Commercia ted 1-Hou 1-Sus PROGRAM, IF ANY. nabove is true and comp Income	14# in the Tubb for d stimulate as ud and fresh wa al mud with min sp 1-LBG PROPOSAL IS TO DEEPEN O Delete to the best of my at TitleAssist.	2600' mation. After m necessary in att ter. imum properties 1-W. Stafford, PLUG BACK, GIVE DATA ON powledge and belief. Admin. Analyst	Circ. Tieback reaching tempting for saf APPR Hou PER UN PRESENT PRO	to 8-5/ TD, log commerc e hole co OVAL VALI MIT EXPIRE LESS DRILE	Surf. B" Bottom 8-5 s will be ial onditions. D FOR <u>90</u> D S <u>1-1-87</u> ING UNDERWAY AND PROPOSED NEW PI	
Propose to drill run and evaluated production. MUD PROGRAM: 0' BOP Attached Gas is not dedica 0+2-NMOCD, SF	and equip well Perforate an -700' Native m -TD Commercia ted 1-Hou 1-Sus OPOSED PROGRAM: IF I PROGRAM, IF ANY. Niabove 1s true and comp Mercian State Use)	14# in the Tubb for d stimulate as ud and fresh wa al mud with min sp 1-LBG PROPOSAL IS TO DEEPEN O Delete to the best of my at TitleAssist.	2600' mation. After m necessary in att ter. imum properties 1-W. Stafford, R PLUG BACK, GIVE DATA ON powledge and bellef.	Circ. Tieback reaching tempting for saf APPR Hou PER UN PRESENT PRO	to 8-5/ TD, log commerc e hole co POVAL VALI MIT EXFINIT LESS DRILL	Surf. B" Bottom 8-5 s will be ial onditions. D FOR <u>90</u> D S <u>1-1-87</u> ING UNDERWAY AND PROPOSED NEW PF	

STATE OF NEW MEXICO ENERGY AND MINERALS DEFARTMENT

۰.

!

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-102 Revised 10-1-73

		All distances must to	from the o	uter bounderses of	the Section	n	.
Coperator AMOCO			HUTCHERSON B				Well No. B 17
Unit Letter	Section	Township	Ha	nge	County		
G	· 21	T 19 N	٦ F	234 E		UNION	
Actual l'astage Loc	ation of Well;						
1980	feet from the NO	RTH line and	1974	t tee	t from the	EAST	line
Ground Level Elev.	Producting Form		Peol				Dedicated Acreage:
4828	1	ubb		Und. Tu	ıbb	A	A 160
		ed to the subject w dedicated to the wel					
interest an 3. If more that	d royalty). n one lease of di ammenitization, ur		dedicate ing. etc?	d to the well,			all owners been consoli-
If answer i this form if No allowab	s "no," list the o necessary.) le will be assigned	wners and tract desc d to the well until all	riptions l interes	which have ac	onsolida	ted (by com	munitization, unitization, approved by the Division.
		086/		1974		toined her best of my Name Position Assist Company	CERTIFICATION ertify that the information con- ein is true and complete to the knowledge and belief. for Areer . Admin. Analyst
	SER 3 0 1530]	Amoco Date	Production Company 9-26-80
						shown on t notes of e under my s	certify that the well location his plat was plotted from field atual surveys made by me or upervision, and that the same d correct to the Lest of my and belief.
	 				6	and br Lord	A Shally
12802 Brancher	Participation	and the second s				Certificate He	·
330 660 40	1320 1060 1980	2310 2640 2000	1500	1000 800	¢ 0		



- 1. Blow-out preventers and master valve to be fluid operated and oil fittings must be in good condition, 3,000# W.P. (6,000 p.s.i. test), minimum.
- 2. Equipment through which bit must pass shall be as large as the inside diameter of the casing that is being drilled through.
- 3. Nipple above blow-out preventer shall be same size as casing being drilled through. 4.
- Kelly cock required, 3,000# W.P. (6,000 p.s.i. test) minimum. 5. OMSCO or comparable safety valve must be available on rig floor at all times with proper connection or sub, 3,000# W.P. (6,000 p.s.i. test), mininum.
- Blow-out preventers and master valve while drilling intermediate hole to 6. 6000' may be 2,000= W.P. (4,000 p.s.i. test), minimum. 7.
- Choke assembly, beyond second valve from cross, may be positioned (Optional) outside of derrick foundation. 8.
- Spool or cross may be climinated if connections are available in the lower part of the blow-out preventer body.
- 9. Plug valves gate valves are optional. Valves shown as 2" are minimum size.
- 10. Casing head and casing head spool, including attached valves, to be furnished by Anoco.
- 11Rams in preventers will be installed as follows: When drilling, use:

Top Preventer - Drill pipe rams Bottom Preventer - Blind rams or master valve

- When running casing, use:
 - Top Preventer Casing raπs Bottom Preventer - Blind rars or master valve



BLOWOUT PREVENTER HOOK-UP

AMOOD FROM MORENESS IN

EXHIBIT D-I MODIFIED