

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-059-20094
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name BDCDGU-1935
8. Well No. 041
9. Pool name or Wildcat Tubb

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER C02	
2. Name of Operator Amoco Production Company	
3. Address of Operator PO Box 606, Clayton, NM 88415	
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>4</u> Township <u>19N</u> Range <u>34E</u> NMPM Union County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4635' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Install Casing Liner</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1935-041G
1. MIRUSU 1/27/97
2. KILL WELL
3. LD 2 7/8 TBG, ON/OFF TOOL, PKR, TAILPIPE
4. RUN TAILPIPE, PKR, ON/OFF TOOL, 2 3/8 TBG
5. PSA 2083'
6. RUN & SET BLK PLG IN PROFILE @ 2080'
7. BLEED TBG & CSG TO 0 PSI
8. REL ON/OFF TOOL & PU TBG

9. RUN POLY BORE GAUGE RING
10. RUN POLYLINER TO 2080'
11. SHUT IN OVER NIGHT
12. INSTALL WELLHEAD BONNETT
14. RDMOSU 1/31/97
15. RWTP 1/31/97

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy E Prichard TITLE Field Foreman DATE 2/27/97
TYPE OR PRINT NAME Billy E Prichard TELEPHONE NO. 374-3053

(This space for State Use)

APPROVED BY Ry E Johnson TITLE DISTRICT SUPERVISOR DATE 3/17/97
CONDITIONS OF APPROVAL, IF ANY: