Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

DISTRICTI P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATIO	
2040 FacileCo	30,050,20004
DISTRICT II Santa Fe, N. P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
CLINDRY NOTICES AND REPORTS ON WEI	V/////////////////////////////////////
SUNDRY NOTICES AND REPORTS ON WEL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PE (FORM C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A 7 Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL OTHER CO2	BDCDGU-1935
2. Name of Operator	8. Well No.
Amoco Production Company	041
3. Address of Operator	9. Pool name or Wildcat
PO Box 606, Clayton, NM 88415	Tubb
Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u>	Line and 1980 Feet From The East Line
Section 4 Township 19N Ra	inge 35E NMPM Union County
4635' GR	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB
OTHER: Install Casing Liner X	OTHER:
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	
MIRUSU RUN & SET 1.625" BLANKING PLG IN PROFILE BLEED TBG TO 0 PSI NUBOP RELEASE ON/OFF TOOL SWAB CSG DOWN, REC AS MUCH FLUID AS POSSIBLE LAYDOWN FG TBG RUN POLYBORE GAUGE RING OPTION #1 IF GAUGE RING GOES & LOOKS OK WHEN PULLED: RUN 10-3 1/8" DRILL, COLLARS (COLLARS EQUIPPED WITH 2 7/8" PAC BOX ON TOP); RIG UP ROLLER REDUCTION	UNIT; RUN POLY LINER TO TOP OF PKR; FISH DRILL COLLARS FROM POLYLINER W/TBG FUSE ON WELLHEAD FLANGE; INSTALL SS B-1 ADAPTER & MASTER VALVE; INSTALL METER RUN; RU LUBRICATOR & FISH BLANKING PLUG; RETURN WELL TO PRODUCTION; RDMOSU OPTION #2 IF GAUGE RING DOES NOT MAKE IT TO PKR DEPTH OR COMES OUT WITH SIGNS OF CSG DAMAGE, RERUN 3 1/2" FG PRODUCTION TBG; LATCH ON TO PKR; FISH BLANKING PLUG; PRESS TEST CSG & PKR TO 500 PSI; RETURN WELL TO PRODUCTION; RDMOSU
I hereby certify that the information above is true and complete to the best of my knowledge and b	
SIONATURE BULL E-Prulum TITL	Field Foreman 2/27/97
TYPEOR FRINT NAME Billy E Prichard	ТЕЦЕРНОМЕ NO. 374–3053
(This space for State Use)	
APPROVED BY TY COMMENT TITLE DISTRICT SUPERVISOR 3/17/87	