

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

| |
|---|
| WELL API NO. 30-059-20111 |
| 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No. |

| | |
|--|---|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER CO2 | 7. Lease Name or Unit Agreement Name BOCDGU-2035 |
| 2. Name of Operator Amoco Production Company | 8. Well No. 281 |
| 3. Address of Operator PO Box 606, Clayton, NM 88415 | 9. Pool name or Wildcat Tubb |
| 4. Well Location Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line Section 28 Township 20N Range 35E NMPM Union County | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4640' GR | |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Install Casing Liner ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2035-281F

1. MIRUSU 2/22/97
2. RUN & SET BLK PLG
3. BLEED TBG TO 0 PSI
4. NU BOP
5. RUN POLYBORE GAUGE RING TO 2116'
6. PULL GAUGE RING
7. SNUE TBG, PKR, TAILPIPE OUT OF HOLE
8. RETURN WELL TO PRODUCTION 2/23/97
9. RDMOSU 2/25/97
10. FLOW WELL UP CSG 13 DAYS
11. MIRUSU 3/9/97

12. RUN & SET INFL BRIDGE PLG @2105'
13. BLEED CSG TO 0 PSI
14. RUN 9-3 1/8 DC
15. RUN POLYLINER TO 2105'
16. RUN TOOL, 2 3/8 TBG, CATCH DC
17. LAY DOWN TBG & DC
18. ND BOP
19. INSTALL WELLHEAD BONNETT
20. PU INFL BP
21. RDMOSU 3/11/97
22. RETURN WELL TO PRODUCTION 3/11/97

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy E. Prichard TITLE Field Foreman DATE 3/13/97
TYPE OR PRINT NAME Billy E Prichard TELEPHONE NO. 374-3053

(This space for State Use)

APPROVED BY Ry E. Johnson TITLE DISTRICT SUPERVISOR DATE 3/21/97
CONDITIONS OF APPROVAL, IF ANY: