

Submit 3 Copies
Appropriate
strict Office

State of New Mexico
Energy, Minerals, and Natural Resources Department

Form C-103
Revised 1-1-89

STRICT I

O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

STRICT II

O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

STRICT III

00 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-059-20131

5. Indicate Type of Lease

STATE ☐ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well

OIL
WELL ☐

GAS
WELL ☐

OTHER CO2

Name of Operator

AMOCO PRODUCTION COMPANY

8. Well No.

1835-311K

Address of Operator

P.O. Box 303, AMISTAD, NEW MEXICO 88410

9. Pool name or Wildcat

BRAVO DOME CO2 GAS UNIT

Well Location

Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line
Section 31 Township 18N Range 35E NMPM Union County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4605 GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
WILL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations
SEE RULE 1103

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

MIRUSU, kill well as necessary, NUBOP, release packer, lay down production tubing and packer, run workstring to 2,432 feet, spot 8 sacks of cement, pull workstring, WOC, run workstring, tag cement, cement should be above 2,369 feet, pressure test casing to 500 psi, displace casing with mud laden fluid, pull workstring to 1,823 feet, spot 11 sacks of cement, pull workstring to 30 feet and fill casing with cement, NDBOP, cut off wellhead, install PXA marker, RDMOSU, cut off well anchors and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

NATURE D. Holcomb TITLE Field Foreman DATE 8-18-99
PE OR PRINT NAME Danny J. Holcomb TELEPHONE NO (505) 374-3010
This space for State Use)
PROVED BY R. J. E. [Signature] TITLE DISTRICT SUPERVISOR DATE 8/23/99
CONDITIONS OF APPROVAL, IF ANY: