Submit 3 Copies	State of New	Mexico	Form C-103
to Appropriate			Revised 1-1-89
District Office	537	•	
	OIL CONSERVAT	ION DIVISION	WELL API NO.
DISTRICT I			
P.O. Box 1980, Hobbs, NM 88240			
P.O. Drawer DD, Artesia, NM 88210	Santa re, New Mexico	9 8/204-2000	
P.O. Drawer DD, Artesia. SM 66210			
DISTRICT III			6. State Off & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410			
'			7. Lease Name or Unit Agreement Name
i			
1. Type of Well			BRAVO DOME CO2 GAS UNIT
Cr C	OIL CONSERVATION DIVISION  OIL CONSERVATION DIVISION  P.O. Box 2088  Santa Fe, New Mexico 87504-2088  Santa Fe, New Mexico 87504-2088  Santa Fe, New Mexico 87504-2088  SINDREY NOTICES AND REPORTS ON WELLS  OIL VAC. NM 37118  SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  OIL USB INHA FORMATOR REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  OFFICE OF THE COST OFFICE		
	CELL OTHER		8 Well No
2. Name of Operator			
	COMPANT		
3. Address of Operator			
P.O. Box 303, AMIST	AD, NEW MEXICO 88410		BIOCO BONE CO2 GAG CITIT
4. Well Location	rero B. B. Th. Viele	Time and 1650	Fact From The Fact Line
Unit Letter G :			
Section 21			MPM Union County
II. Che	ck Appropriate Box to Indic	ate Nature of Notice, Re	port, or Other Data
NOTICE OF	FINTENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OP	NS PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE FEAINS		<u> </u>
PULL OR ALTER CASING		CASING TEST AND CEMEN	II JOB []
OTHER:		OTHER:	
12. Describe Proposed or Completed Opera	tions (Clearly state all pertinent d	letails, and give pertinent dates, including	ng estimated date of starting any proposed work)
SEE RULE 1103.			
MIRUSU, kill well as nece	ssary, NUBOP, release packer	r, lay down production tubin	g and packer, run cast iron bridge plug
with wireline, set CIBP at	2,552 feet, run workstring, disp	lace casing with corrosion i	nhibited fluid, pressure test casing to
500 psi, cap CIBP with 5	sacks of class C cement, pull w	orkstring to 2,164 feet, spo	t 12 sacks of cement, pull workstring to
	ment, NDBOP, RDMOSU, cut o	on wellnead, Install PXA ma	rker, cut off well anchors and clean
location.			
I hereby certify that the information above	e is true and complete to the best of my kno	wledge and belief.	
SIGNATURE	tolione TITLE	Field Foreman	DATE 3-6-00
TYPE OF PRINT NAME DARRY	oloomb		TELEPHONE NO. (505) 374-3010
	Jicon j		(000) 074-0010
(This space for State Use) APPROVED BY	TITLE	DISTRICT SUPER	11571 DATE 3/10/00
CONDITIONS OF APPROVAL IF ANY.		woverson with his	F 110 4 13