

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103 -
Revised 12-1-73

3a. Indicate Type of Lease
State ☐ Fee ☐
3. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER- CO2
2. Name of Operator
AMOCO PRODUCTION COMPANY
3. Address of Operator
P. O. Box 68, Hobbs, NM 88240
4. Location of well
UNIT LETTER G 1650 North 1650
FEET FROM THE LINE AND FEET FROM
THE East LINE, SECTION 6 TOWNSHIP 19-N RANGE 34-E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.)
4960' GL
12. County
Union

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to reperforate the Tubb formation then fracture stimulate to increase production.

MIRU-SU. Kill well w/2% KCL fresh water. POH w/production equip. Perforate the following Tubb intervals w/a 4" casing gun, 2 JSPF at 180° phasing: 2360-2417, 2422-2440, 2448-2457, 2460-2472, 2481-2498, 2502-2507, 2536-2563, 2572-2580. RIH w/treating packer and 3-1/2" J-55 workstring. Above packer place a Baker 2.875" sidemount with a Lynes Sentry MK9-E downhole pressure-temperature gauge. Set packer at 2000'. Prepare to frac well with 40# HEC Gel, liquid CO2 and 8/16 Brady sand. Mix gel in 2% KCL fresh water.

0+2-NMOCDF, SF 1-R.A. Sheppard HOU. Rm. 20.156 1-J.F. Nash HOU. Rm. 17.188 1-SBB
1-Amerada Hess 1-Amerigas 1-Cities Service 1-Conoco 1-CO2 in Action 1-Shell
1-Exxon 1-WF, Hobbs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Steve Brownlee TITLE Admin. Analyst DATE 11-14-86
APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 11-20-86
CONDITIONS OF APPROVAL, IF ANY:

Frac down tubing as follows:

<u>Stage</u>	<u>Gel Vol Bbls</u>	<u>Clean Rate (BPM)</u>	<u>Blender Conc. (PPG)</u>	<u>CO2 Vol Bbls</u>	<u>Rate BPM</u>
Pad	152	14	0.0	229	21
First	29	14	10.0	43	21
Second	48	14	12.5	71	21
Third	76	14	15.0	114	21
Flush	8	14	0.0	12	21
Total					

Shut well in for 2 hrs after frac job. Flow well back to flow tank to recover load water overnight. Clean out sandfill to 2640' with bulldog bailer. RIH w/production equip. Load backside w/packer fluid and pressure test annulus to 500#. Swab well down to recover load. RDMO-SU. Return well to production.

2 AUG 02 12 00 PM