Submit 3 Caples	State of New Mexico	Form C-103
to Appropriate	Energy, Minerals, and Natural Resources Department	Revised 1-1-89
District Office		
<u>DISTRICT I</u>	OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088	30-059-20257
<u>DISTRICT II</u>	Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
P.O. Drawer DD, Artesia, NM 88210		STATE FEE
DISTRICT III		6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410		
	NOTICES AND REPORTS ON WELLS	
	SALS TO DAILL OR TO DEEPEN OR PLUG BACK TO A Servoir. Use "application for permit"	7. Lease Name or Unit Agreement Name
	FORM C-101) FOR SUCH PROPOSALS.)	A Zease Ivalue of Olin Agreement Ivalue
1. Type of Well		BRAVO DOME CO2 GAS UNIT
	SAS OTHER CO2	
2. Name of Operator	Units CO2	8. Well No.
AMOCO PRODUCTION COMPA	ANY	2431-271K
3 Address of Operator		9. Pool name or Wildcat
P.O. Box 303, AMISTAD,	NEW MEXICO 88410	BRAVO DOME CO2 GAS UNIT
4. Well Location		
	1980 Feet From The SOUTH Line and 1980	Feet From The WEST Line
Section 27	Township 24N Range 313 NMF	
	10. Elevation (Show whether DF, RKB, RT, GR, etc.)	County
	10. Elevation (Show whether Dr., RRB, RT, GR, etc.) 5658 GR	
Che	eck Appropriate Box to Indicate Nature of Notice, Repo	ort, or Other Data
	•	
NOTICE OF INT		JENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB	
OTHER:	OTHER:	
12. Describe Proposed or Completed Operati		Parting any granged work!
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.		
MIRUSU,Kill well as necessary, NUBOP,Rel pkr,LD production tbg and pkr,Run Cast iron BP with		
wireline, Set CIBP @ 2457 ft.,Run tbg, Disp csg with mud laden fluid,Prs tst csg to 500psi,		
Cap CIBP with 9 sx cmt, Pull tbg to 2056 ft, Spot 13 sx cmt, Pull tbg to 30ft, Fill csg with cmt,		
NDBOP,Cut off wellhead,Install PXA marker,RDMOSU, Cut off SU anchors,Clean location		
L hereby certify that the information above is true an	nd complete to the best of my knowledge and belief.	
IGNATURE DU	7 C. V. TILE Operations Specialist	DATE 1/20/98
YPE OR PRINT NAME 8. E. Prichard	7/1 //	TELEPH ONE NO. (505) 374-3053
(This space for State Use) APPROVED BY DATE 2-5-98		
CONDITIONS OF APPROVAL, IF ANY		
/ /	//	