## Submit 3 Copies

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico

Form C-103 Revised 1-1-89

District Office DISTRICT I					
77 AA TT 11 AA AA	O	L CONSI	ERVATION	DIVISION	WELL ADLING
O. Box 1980, Hobbs, NM 88	8240	P.O.Box 2088			WELL API NO.
DISTRICT II	69310	Santa Fe, I	New Mexico 87	504-2088	3005920303
O.O. Drawer DD, Artesia, NM	88210				5. Indicate Type of Lease  STATE  FEE
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, N	M 87410				6. State Oil & Gas Lease No.
Ooo Ido Diabou Nei, Imee, Im					L-6244
SUNDR					
(DO NOT USE THIS FORM	FOR PROPOS	SALS TO DRIL	LL OR TO DEEPEI LICATION FOR PI	N OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
			PROPOSALS.)	-UiAii i	Bravo Dome Carbon Dioxide Gas Unit - 2233
. Type of Well					
OIL WELL	GAS X		OTHER	CO2	
. Name of Operator					8. Well No.
moco Production Company	1				271F
. Address of operator					9. Pool name or Wildcat
P.O. Box 606 Clay	ton	N. Mex.	88415		Tubb
. Well Location			144		000
Unit Letter F	1960	Feet From The	west	Line and 20	D29 Feet From The North Lin
outin 21	7	Township	T 22 N R	ange R 33 E	NMPM Union County
Section 27	<i>,</i>			er DF, RKB, RT, GR, etc.)	THAT SHOW COMMY
			(=====	4781	
1. Che	eck Appro	priate Box	to Indicate I	Nature of Notice, R	eport, or Other Data
	OF INTEN	-		i	JBSEQUENT REPORT OF:
ERFORM REMEDIAL WORK	:	LUG AND AB	ANDON	REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON		HANGE PLAN	ıs	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
EMPORARILI ABANDON					
PULL OR ALTER CASING				CASING TEST AND C	EMENT JOB
PULL OR ALTER CASING					
OTHER:				OTHER:	
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Com	pleted Operation			OTHER:	
OTHER:	pleted Operation			OTHER:	
DTHER:	npleted Operation	ons (Clearly sta	ue all pertinent deu	OTHER:	, including estimated date of starting any proposed
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450	spud a 12-1/	ons (Clearly sta 4 surface hole A with additiv	te all pertinent deta on 6/3/93. Drill res. Circulated 1	OTHER:  ails, and give pertinent dates  ded to 710. Ran 17 joints 05 sacks to the surface.	, including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran	spud a 12-1/ sacks class a 73 joints of	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas	o on 6/3/93. Drillyes. Circulated 1	OTHER:  ails, and give pertinent dates  ded to 710. Ran 17 joints 05 sacks to the surface.  ing and set at 2158. Cer	, including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a nented with 420 sacks of class A with additives.
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran Circulated 30 sacks or cei	spud a 12-1/ sacks class n 73 joints of ment to the s	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea	o on 6/3/93. Drill yes. Circulated 1 as production cas ased drilling rig 6/	oTHER:  ails, and give pertinent dates  ded to 710. Ran 17 joints 05 sacks to the surface. ing and set at 2158. Cer 16/93. Moved in and rigg	, including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. ad up service unit 7/2/93. Tested casing to 500
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran Circulated 30 sacks or cepsi and held ok. Drilled co	spud a 12-1/ sacks class a 73 joints of ment to the s	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea to 2183. Blev	o on 6/3/93. Drilly yes. Circulated 1 as production cas ased drilling rig 6/ w well dry. Drille	oTHER:  ails, and give pertinent dates  ded to 710. Ran 17 joints 05 sacks to the surface. ing and set at 2158. Cer 6/93. Moved in and rigg d with air 2183'-2191'.	including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. ad up service unit 7/2/93. Tested casing to 500 Drilling break at 2191' to 2265'. Flowed well on
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran Circulated 30 sacks or celpsi and held ok. Drilled ce 2" flow line. Drilled 2265	spud a 12-1/ ) sacks class a 73 joints of ment to the s ement 2127; 5' to 2296'.	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea to 2183. Blev Flowed well o	o on 6/3/93. Drill ves. Circulated 1 is production cas used drilling rig 6/ w well dry. Drille in 2" flow line. N	oTHER:  ails, and give pertinent dates  ded to 710. Ran 17 joints 05 sacks to the surface. ing and set at 2158. Cer 6/93. Moved in and rigg d with air 2183'-2191'.	, including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. ad up service unit 7/2/93. Tested casing to 500
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8* hole to 2158. Ran Circulated 30 sacks or cepsi and held ok. Drilled co	spud a 12-1/ ) sacks class a 73 joints of ment to the s ement 2127; 5' to 2296'.	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea to 2183. Blev Flowed well o	o on 6/3/93. Drill ves. Circulated 1 is production cas used drilling rig 6/ w well dry. Drille in 2" flow line. N	oTHER:  ails, and give pertinent dates  ded to 710. Ran 17 joints 05 sacks to the surface. ing and set at 2158. Cer 6/93. Moved in and rigg d with air 2183'-2191'.	including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. ad up service unit 7/2/93. Tested casing to 500 Drilling break at 2191' to 2265'. Flowed well on
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran Circulated 30 sacks or celpsi and held ok. Drilled ce 2" flow line. Drilled 2265	spud a 12-1/ ) sacks class a 73 joints of ment to the s ement 2127; 5' to 2296'.	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea to 2183. Blev Flowed well o	o on 6/3/93. Drill ves. Circulated 1 is production cas used drilling rig 6/ w well dry. Drille in 2" flow line. N	oTHER:  ails, and give pertinent dates  ded to 710. Ran 17 joints 05 sacks to the surface. ing and set at 2158. Cer 6/93. Moved in and rigg d with air 2183'-2191'.	including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. ad up service unit 7/2/93. Tested casing to 500 Drilling break at 2191' to 2265'. Flowed well on
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran Circulated 30 sacks or celpsi and held ok. Drilled ce 2" flow line. Drilled 2265	spud a 12-1/ ) sacks class a 73 joints of ment to the s ement 2127; 5' to 2296'.	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea to 2183. Blev Flowed well o	o on 6/3/93. Drill ves. Circulated 1 is production cas used drilling rig 6/ w well dry. Drille in 2" flow line. N	oTHER:  ails, and give pertinent dates  ded to 710. Ran 17 joints 05 sacks to the surface. ing and set at 2158. Cer 6/93. Moved in and rigg d with air 2183'-2191'.	including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. ad up service unit 7/2/93. Tested casing to 500 Drilling break at 2191' to 2265'. Flowed well on
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran Circulated 30 sacks or celpsi and held ok. Drilled ce 2" flow line. Drilled 2265	spud a 12-1/ ) sacks class a 73 joints of ment to the s ement 2127; 5' to 2296'.	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea to 2183. Blev Flowed well o	o on 6/3/93. Drill ves. Circulated 1 is production cas used drilling rig 6/ w well dry. Drille in 2" flow line. N	oTHER:  ails, and give pertinent dates  ded to 710. Ran 17 joints 05 sacks to the surface. ing and set at 2158. Cer 6/93. Moved in and rigg d with air 2183'-2191'.	including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. ad up service unit 7/2/93. Tested casing to 500 Drilling break at 2191' to 2265'. Flowed well on
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran Circulated 30 sacks or celpsi and held ok. Drilled ce 2" flow line. Drilled 2265	spud a 12-1/ ) sacks class a 73 joints of ment to the s ement 2127; 5' to 2296'.	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea to 2183. Blev Flowed well o	o on 6/3/93. Drill ves. Circulated 1 is production cas used drilling rig 6/ w well dry. Drille in 2" flow line. N	oTHER:  ails, and give pertinent dates  ded to 710. Ran 17 joints 05 sacks to the surface. ing and set at 2158. Cer 6/93. Moved in and rigg d with air 2183'-2191'.	including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. ad up service unit 7/2/93. Tested casing to 500 Drilling break at 2191' to 2265'. Flowed well on
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran Circulated 30 sacks or celpsi and held ok. Drilled ce 2" flow line. Drilled 2265	spud a 12-1/ ) sacks class a 73 joints of ment to the s ement 2127; 5' to 2296'.	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea to 2183. Blev Flowed well o	o on 6/3/93. Drill ves. Circulated 1 is production cas used drilling rig 6/ w well dry. Drille in 2" flow line. N	oTHER:  ails, and give pertinent dates  ded to 710. Ran 17 joints 05 sacks to the surface. ing and set at 2158. Cer 6/93. Moved in and rigg d with air 2183'-2191'.	including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. ad up service unit 7/2/93. Tested casing to 500 Drilling break at 2191' to 2265'. Flowed well on
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran Circulated 30 sacks or celpsi and held ok. Drilled ce 2" flow line. Drilled 2265	spud a 12-1/ spud a 12-1/ sacks class a 73 joints of ment to the s ement 2127; to 2296'.	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea to 2183. Blev Flowed well o	o on 6/3/93. Drill ves. Circulated 1 is production cas used drilling rig 6/ w well dry. Drille in 2" flow line. N	oTHER:  ails, and give pertinent dates  ded to 710. Ran 17 joints 05 sacks to the surface. ing and set at 2158. Cer 6/93. Moved in and rigg d with air 2183'-2191'.	including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. ad up service unit 7/2/93. Tested casing to 500 Drilling break at 2191' to 2265'. Flowed well on
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran Circulated 30 sacks or celpsi and held ok. Drilled ce 2" flow line. Drilled 2265	spud a 12-1/ ) sacks class a 73 joints of ment to the s ement 2127; 5' to 2296'. oleted and wa	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea to 2183. Blev Flowed well o sitting on sales	o on 6/3/93. Drill yes. Circulated 1 is production cas used drilling rig 6, w well dry. Drille in 2" flow line. No	oTHER:  ded to 710. Ran 17 joints of sacks to the surface. ing and set at 2158. Cer of/93. Moved in and rigg d with air 2183'-2191'. Impled down blow out pre	including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. ad up service unit 7/2/93. Tested casing to 500 Drilling break at 2191' to 2265'. Flowed well on
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran Circulated 30 sacks or ceipsi and held ok. Drilled cc 2" flow line. Drilled 2265 unit 7/3/93. Well is comp	spud a 12-1/ ) sacks class a 73 joints of ment to the s ement 2127; 5' to 2296'. oleted and wa	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea to 2183. Blev Flowed well o sitting on sales	o on 6/3/93. Drill yes. Circulated 1 is production cas used drilling rig 6/ w well dry. Drille in 2" flow line. No hook up.	other:  ails, and give pertinent dates  led to 710. Ran 17 joints 05 sacks to the surface. ing and set at 2158. Cer 16/93. Moved in and rigg d with air 2183'-2191'. lippled down blow out pre	including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. ad up service unit 7/2/93. Tested casing to 500 Drilling break at 2191' to 2265'. Flowed well on
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Comwork.) SEE RULE 1103.  Moved in drilling unit and 710. Cemented with 450 7-7/8" hole to 2158. Ran Circulated 30 sacks or cepsi and held ok. Drilled co. 2" flow line. Drilled 2265 unit 7/3/93. Well is comp	spud a 12-1/ ) sacks class a 73 joints of ment to the s ement 2127; 5' to 2296'. oleted and wa	ons (Clearly sta 4 surface hole A with additiv 4.5" fiberglas surface. Relea to 2183. Blev Flowed well o sitting on sales	o on 6/3/93. Drill yes. Circulated 1 is production cas used drilling rig 6, w well dry. Drille in 2" flow line. No	other:  ails, and give pertinent dates  led to 710. Ran 17 joints 05 sacks to the surface, ing and set at 2158. Cer 6/93. Moved in and rigg d with air 2183'-2191'.  lippled down blow out pre  my knowledge and belief.  TITLE Administra	including estimated date of starting any proposed of 8.625°, 24#. K-55 surface casing and set at Pressure tested casing to 500 psi. Drilled a mented with 420 sacks of class A with additives. and up service unit 7/2/93. Tested casing to 500 Drilling break at 2191' to 2265'. Flowed well on eventer and nippled up wellhead. Rig down services.