

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals, and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-059-20304

5. Indicate Type of Lease

STATE ☐

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well

OIL
WELL ☐

GAS
WELL ☐

OTHER

CO2

7. Lease Name or Unit Agreement Name

BRAVO DOME CO2 GAS UNIT

Name of Operator

AMOCO PRODUCTION COMPANY

8. Well No.

2233-281F

Address of Operator

P.O. Box 303, AMISTAD, NEW MEXICO 88410

9. Pool name or Wildcat

BRAVO DOME CO2 GAS UNIT

Well Location

Unit Letter F : 1909 Feet From The West Line and 1903 Feet From The North Line
Section 28 Township 22N Range 33E NMPM Union County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4804 GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

WELL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

SEE RULE 1103.

10-11-99

MIRUSU, kill well with fresh water, NUBOP, run 2 3/8" workstring to 2,334 feet, spot 45 sacks of Class C cement, pull workstring and WOC. Run workstring and tag cement at 1737', bottom plug 2334' to 1737'. Pressure test casing to 500 psi, ok. Displace casing with fresh water with corrosion inhibited fluid, pull workstring to 30 feet and fill casing with cement, NDBOP, cut off wellhead, install PXA marker, RDMOSU, cut off well anchors and clean location.

2/8/00
OK REJ

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

D. J. Holcomb

TITLE Field Foreman

DATE 10-13-99

NAME OR PRINT NAME

Danny J. Holcomb

TELEPHONE NO (505) 374-3010

This space for State Use

APPROVED BY

R. E. Johnson

TITLE

DISTRICT SUPERVISOR

DATE

2/10/00

CONDITIONS OF APPROVAL, IF ANY