Submit 3 Copies to Appropriate	State of New Mexico Energy, Minerals, and Natural Resources Department		Form C-103 Revised 1-1-89
DISTRICT   P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-059-20376
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease STATE FEE STATE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name
1. Type of Well	(FORM C-101) FOR SUCH PROPOSALS.)	002	BRAVO DOME CO2 GAS UNIT
2. Name of Operator  AMOCO PRODUCTION COMP	WELL OTHER	C02	8. Well No. 1935-282E
3. Address of Operator P.O. Box 303, AMISTAD,	NEW MEXICO 88410		9. Pool name or Wildcat BRAVO DOME CO2 GAS UNIT - Tubb
4 Well Location Unit Letter E	1674 Feet From The North	Line and 994	Feet From The West Line
Section 28	Township 19N  10. Elevation (Show whe 4599	Range 35E NMF  ther DF, RKB, RT, GR, etc.)  GL	PM Union County
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB	
OTHER: COMPLETION X			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  SEE RULE 1103.			
1) 5/12/98 - Move in rig up service unit. Swab well down to 1800'. Rig down, move out service unit.			
2) 5/13/98 - Rig up wireline and run thermal multigate decay log. 1900' - 2247'.			
3) 5/14/98 - Rig up wireline and run 4" OD guns. Perf 2056' - 2200' with 4 SPF. Flow well.			
4) 5/20/98 - Rig up frac equipment. Foam frac with CO2 <sub>,</sub> 69300# 12/20 sand at 40 bpm at 1400 psi.			
5) Flow well to pit for 2 days. Turn well to production 5/23/98.			
hereby certify that the information above is trips and complete to the best of my knowledge and belief.			
IGNATURE	$\mathcal{L}_{i}$	Field Team Leader	DATE 6/9/98
YPE OR PRINT NAME D. J. Holcomb			TELEPHONE NO. (505) 374-3010
This space for State Use)  PPROVED BY  TITLE DISTRICT SUPERVISOR DATE 6/15/98			
CONDITIONS OF APPROVAL, IF ANY:			