

Log 6925

COUNTY Union

COMPANY Gruemmer Indian Carbonic, Ltd.

LOCATION ($\frac{1}{4}$) SE SE

SEC. 33 T. 30N R. 29E

660 feet from east line and

660 feet from south line of section

COMMENCED 10-24-53

COMPLETED 1-14-54

ABANDONED

REMARKS Depth Cleaned out 2461

Formation	Bottom, Feet
-----------	--------------

Formation	Bottom, Feet
-----------	--------------

Dakota	0
Morrison	155
Todilto	453
Entrada	513
Triassic	570
Permian	1045
Alibates	1074
Blaine	1295
Glorieta	1340
Clear Fork	1490
Granite Wash	1780