

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Budget Bureau No. 1094-
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO

NM 61418

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
SWEPT ET AL MANGAS
MOUNTAINS FEDERAL

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

NW/4 SW/4 SEC. 21
T3S-R15W

12. COUNTY OR PARISH

CATRON

13. STATE

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

SHELL WESTERN E&P INC.

3. ADDRESS OF OPERATOR

P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

8465' SOUTH & 11,083' EAST OF NW CORNER OF
SEC. 18

(Est) 506' FWL & 2197' FSL SEC. 21

14. ~~XXXXXX~~ API NO.

30-003-20016

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

9034' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

12-03 to 12-04-87: Set 60 sx Cls "H" cmt + .02% HR-7 from 6325' to 6175'. POH to 4895'.
Set 35 sx Cls "H" cmt + 2% CaCl₂ + .3% salt from 4895' to 4795'. WOC 5 hrs.
Tagged TOC @ 4780'. Balance plug set 35 sx Cls "H" cmt from 3896' - 3800'.
Perf'd @ 2050' (4 holes). Sqzd 35 sx Cls "H" cmt behind 9-5/8" csg from
2050' - 1950'. Balance plug set 35 sx Cls "H" inside 9-5/8" csg from 2050' -
1950'. Perf'd @ 892' (4 holes). Set cmt ret @ 782'. Sqzd 35 sx Cls "H"
behind 9-5/8" csg. Sqzd 35 sx Cls "H" cmt inside 9-5/8" csg below ret. Capped
ret w/25 sx Cls "H". Pumped 35 sx Cls "H" into 13-3/8" X 9-5/8" annulus. Bal-
ance plug set 35 sx Cls "H" inside 9-5/8" csg from 54' - 4'. Cut off WH &
welded cap (w/BLM - required info permanently inscribed) on csg.

NOTE: A follow-up Sundry Notice will be submitted upon complete restoration
of site.

18. I hereby certify that the foregoing is true and correct

SIGNED A. J. Fore A. J. FORE

TITLE SUPERVISOR REG. & PERMITS

DATE 1-12-88

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

APPROVED
DATE
PETER W. CHESTER

JAN 20 1988

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA