

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-007-20095
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Castle Rock Park 3118	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER Coal Methane	8. Well No. 311-M		
2. Name of Operator Pennzoil EXploration & Production Company	9. Pool name or Wildcat Wildcat		
3. Address of Operator P.O. Box 2967, Houston, TX 77252			
4. Well Location Unit Letter <u>M</u> : <u>747</u> Feet From The <u>South</u> Line and <u>990</u> Feet From The <u>West</u> Line Section <u>31</u> Township <u>31N</u> Range <u>18E</u> NMPM Colfax County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>8568 Gr</u>			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/02/91 Estimated start of work.

1. Remove surface equipment, pull rods and tubing.
2. Set CIBP @ 1774' with 2 sks (18') class A @ 15.6 ppg.
3. Set CIBP @ 1530' with 12 sks (108') class A @ 15.6 ppg. Fill to surface with Gel mud.
4. Place 6 sks (50') surface plug with class A @ 15.6 ppg.
5. Place well marker, fill pits, remove junk and debris from location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. D. Williamson TITLE Operations Superintendent DATE 7/09/91

TYPE OR PRINT NAME L. D. Williamson

TELEPHONE NO. 376-2817

(This space for State Use)

APPROVED BY R. E. Johnson DISTRICT SUPERVISOR DATE 7-10-91

CONDITIONS OF APPROVAL, IF ANY: