

Plugging Procedure

Bruce A. Hillman

T-4 Patton Co N7

Sec 18 - 11 - 26

Madison Co -

Set plug from 600' to 712' T.D.

Set plug from 70' to 120'

Set (Coarse plug at surface)

Install Markers