

BERT THOMPSON				#1 Tucumcari 1st Nat'l Bank P-20-8N-22E			
COMPANY				WELL NO.		LEASE	
Loc.	660	fr.	S L	660	fr.	E L	County Guadalupe
Spud.	8-30-59	Comp.	9-29-59	Field Wildcat			
T.D.	6032	P.B.		T.Pay		CSG. RECORD	
I.P.	P & A					Size	Depth
						9-5/8	328
Remarks: Wire line DST Failure. DST 5127						Sax	200
ISIFP ISI SI O Stuck tool in hole no rec							
						Tbg. at	
						FORMATION RECORD	
						Elev. 4804	DF 4799 64
						T.San And	536
						T.Glor	1023
						T.Arkose	3312
						T.Miss	5970
Treatment:						T.Gr	6012
						T.White Horse	288
						T.	
						T.	
						T.	

Co. GUADALUPE POOL WILDCAT STATE N.M. KROENLEIN 13-59

COMPANY Bert Thompson et al - #1 - Tucumcari ELEV. 4804
First Nat'l Bank

LOC (660' FNL & PEL) corr.: 660' FSL & PEL
Sec. 20, T.8-N, R. 22-E
6500' Gr.

ACID OR SHOT	CASING RECORD	TOPS
	9 5/8- 328- 200	White Horse 288
		S. And. 536
		B.S. And. 938
		Glor. 1023
		Tubb 2470
		Ark. 3312
		Miss. 5970
SPD 8-30-59	COMP 9-29-59	
I. P. F & A		
GR GOR TP CP		TP
REMARKS Wire Line DST: 5127' - no rec.		TD 6032 Gr.
		POD