

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-021-20150

5. Indicate Type of LeaseSTATE ☐FEE ☐**6. State Oil & Gas Lease No.****7. Lease Name or Unit Agreement Name**

BRAVO DOME CO2 GAS UNIT

8. Well No.

1833-351G

9. Pool name or Wildcat

BRAVO DOME CO2 GAS UNIT

SUNDRY NOTICES AND REPORTS ON WELLS(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)**1. Type of Well**OIL
WELL ☐GAS
WELL ☐

OTHER

CO2

2. Name of Operator

AMOCO PRODUCTION COMPANY

3. Address of Operator

P.O. Box 303, AMISTAD, NEW MEXICO 88410

4. Well LocationUnit Letter G : 1650 Feet From The North Line and 1650 Feet From The East Line
Section 35 Township 18N Range 33E NMPM Harding County**10. Elevation (Show whether DF, RKB, RT, GR, etc.)**4765' GR**11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data****NOTICE OF INTENTION TO:**PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CAS NG ☐OTHER ☐**SUBSEQUENT REPORT OF:**REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS ☐PLUG AND ABANDONMENT ☒CASING TEST AND CEMENT JOB ☐OTHER ☐**12. Describe Proposed or Completed Operations**

SEE RULE 1103.

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

11/6/99

MIRUSU, kill well with fresh water, NUBOP, release packer, lay down production tubing and packer, run cast iron bridge plug with wireline, set CIBP at 2,518 feet, run workstring, tag CIBP at 2,518 feet, displace casing with fresh water and corrosion inhibitor, pressure test casing to 500 psi, held ok. Cap CIBP with 5 sacks of Class C cement from 2518' - 2470', pull workstring to 1,991 feet, spot 10 sacks of cement from 1991' - 1895', pull workstring to 30 feet, spot 5 sacks of cement from 30' - 3, NDBOP, cut off wellhead, install PXA marker, RDMOSU, cut off well anchors and clean location.

2/7/00
OK REF

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE

TITLE Foreman

DATE 11-8-99

TYPE OR PRINT NAME

Danny J. Holcomb

TELEPHONE NO (505) 374-3050

(This space for State Use)

APPROVED BY

TITLE

DISTRICT SUPERVISOR

DATE

2/10/00

CONDITIONS OF APPROVAL, IF ANY