

G-12-19N-30E: ~~From above~~ to wildcat reported P & A in 1939 without approval from Oil Conservation Commission. Location found - marked by small slag pile, scattered fire bricks, broken wooden "bull wheel" and rig anchors. Apparent location of bore hole marked by 2 1/2" steel pipe which is rigid, presumed cemented in conductor pipe not showing above ground. File will be closed.

C.U. 8- -75

DEC 10 1945
SERIAL FILE FOLDER
No. 11275
BUREAU OF LAND MANAGEMENT
U. S. DEPARTMENT OF THE INTERIOR
WASHINGTON, D. C.