

INSPECTION REPORT

July 17, 1952

Lubbock Machine Co., Inc.

Re: H. B. Colbaugh No. 1
SW/4 Sec. 12-1N-12E
Torrance County

By 12:00 noon today this well had reached a total depth of 1004'. The repaired clutch cited in the previous report was received about five days ago but operations were not resumed until today. This delay was due to the operator's losing time getting leases straightened out. Drilling was resumed today.

The formation at total depth is a granite wash, having a very sandy appearance to the naked eye. Under magnification the cuttings are a clear to rose colored quartz with a great deal of hornblende and/or biotite dispersed in place throughout.

E. A. C.

EUGENE A. CHAVEZ,
Geological Scout - District 4