

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State ☐ For ☒
5. State Oil & Gas Lease No. --
7. Unit Agreement Name --
8. Form or Lease Name J. M. Bennett
9. Well No. 1
10. Field and Pool, or Wildcat undesignated
12. County Union

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐	GAS WELL ☐	OTHER- Carbon Dioxide
Name of Operator Texaco, Inc.		
Address of Operator P. O. Box 728, Hobbs, New Mexico 88240		
Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 27 TOWNSHIP 30-N RANGE 29-E N.M.P.M.		

15. Elevation (Show whether DF, RT, GR, etc.)
6560' (GR)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up.
2. Set CIBP @ 2000' & spot 40' cement plug from 2000' - 1950'.
3. Set 10 sx. Cement plug from 40' - surface.
4. Install Dry Hole Market & Clean Up Location.
5. Well P & A, 12/6/80.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 12/10/80
APPROVED BY Carl Wilcox TITLE SENIOR PETROLEUM GEOLOGIST DATE 3/23/81
CONDITIONS OF APPROVAL, IF ANY