

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-059-20064
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> CO2
2. Name of Operator Amoco Production Company
3. Address of Operator PO Box 606, Clayton, NM 88415

7. Lease Name or Unit Agreement Name BDCDGU-1935
8. Well No. 061
9. Pool name or Wildcat Tubb

4. Well Location
Unit Letter G : 2044 Feet From The North Line and 1980 Feet From The East Line
Section 6 Township 19N Range 35E NMPM Union County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4690' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Install Casing Liner</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- | | |
|---|--------------------------------------|
| 1935-061G | 10. RUN WL & SET PKR @2080' |
| 1. MIRUSU 4/09/97 | 11. RUN 9 - 3 1/8 DC |
| 2. KILL WELL NU BOP | 12. RUN POLYLINER TO 2280' |
| 3. LAY DOWN 2 7/8 FG TBG, PKR, TAILPIPE | 13. RUN TOOL, 2 3/8 TBG, CATCH DC |
| 4. INSTALL WELLHEAD BONNETT | 14. LAY DOWN TBG & DC |
| 5. RD MOSU 4/09/97 | 15. NDBOP |
| 6. RUN POLYBORE GAUGE RING TO 2150' | 16. INSTALL WELLHEAD BONNETT |
| 7. RUN ON/OFF TOOL W/WL | 17. RD MOSU 5/1/97 |
| 8. RUN POLYLINER TO 2184' | 18. RETURN WELL TO PRODUCTION 5/1/97 |
| 9. MIRUSU 4/29/97 | |

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy E. Prichard TITLE Field Foreman DATE 5/29/97

TYPE OR PRINT NAME Billy E Prichard TELEPHONE NO. 374-3053

(This space for State Use)

APPROVED BY Ry Johnson DISTRICT SUPERVISOR DATE 6/24/97

CONDITIONS OF APPROVAL, IF ANY: