

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER- CO2	Bravo	7. Unit Agreement Name Dome Carbon Dioxide Gas Unit
2. Name of Operator Amoco Production Company	Bravo	8. Form of Lease Name Dome Carbon Dioxide Gas Unit
3. Address of Operator P. O. Box 832, Brownfield, TX 79316		9. Well No. 1935-011K
4. Location of well UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 1 TOWNSHIP 19 N RANGE 35 E N.M.P.M.	Bravo	10. Field and Pool, or Whichever Dome Carbon Dioxide Gas Unit 640-Acre Area
15. Elevation (Show whether DF, RT, GR, etc.) 4520' GL		12. County Union

13. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	Perform water test ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To update well file on approved work that was performed and not previously reported. NMOCD approval was obtained on 8-22-86 to perform a water test by venting to atmosphere.

8-31-86 MI X RU separator
9-1-86 Well would not flow to atmosphere
9-2-86 Run dip in BHP survey x MI RUSU
9-3-86 TPC 225 psi x bled down. R swab x IFL 1200 ft from surface x swb 8½ hrs and rec. only slight amount of water. Only slight show of gas after each run. RD X MOSU
9-3-86 and leave well shut in. Unable to flow test well to atmosphere.

Leave well in shut-in status

0+3-NMOCD, SF 1-R. A. Sheppard HOU. Rm 20.156 1-T. Thiel HOU. Rm 3.167 1-DJH
1-Amerada Hess 1-Amerigas 1-Cities Service 1-Conoco 1-Shell 1-Exxon
1-WF, Brownfield 1-WF, Clayton

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED DT Holcomb TITLE Sr. Administrative Analyst DATE 3-25-88

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 3-25-88

CONDITIONS OF APPROVAL, IF ANY:

NO RELOCATION FOR MAINTENANCE OR REPAIR
EXCESSIVE ABANDONMENT STATUS EXCEPT