

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

NO. OF COPIES DESIRED	
DISTRIBUTION	
DATE	
FILE	
U.S. DIST.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (FORM O-101) FOR SUCH PROPOSALS.

OIL WELL GAS WELL CO₂ OTHER

Bravo Dome Carbon Dioxide Gas Unit

1. Name of Operator
Amoco Production Company

Bravo Dome Carbon Dioxide Gas Unit 1935

2. Address of Operator
P. O. Box 68, Hobbs, NM 88240

3. Well No.
331

4. Location of Well
UNIT LETTER F 1880 FEET FROM THE North LINE AND 1980 FEET FROM

10. Field and Pool, or Wellcut
Und. Tubb

THE West LINE, SECTION 33 TOWNSHIP 19-N RANGE 35-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
4540 GL

12. County
Union

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Name Change <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1107.

Name changed from Leak No. 1
to Bravo Dome Carbon Dioxide Gas Unit 1935 Well No. 331

0+2 NMOC-D-SF 1-Hou 1-Susp 1-BD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
Bob Davis Admin. Analyst DATE 4-13-81