

4-29-83

Memo

From
CARL ULVOG
Chief Geologist

To File: B-6-31N-34E

Inspected location. Pit not filled,
some pipe and junk on location.
Rancher (Farr) not present.
Advised Diane that bond can
not be released.

CU

Problem with bond: Location
given as 1845' FN & 1650' FE
Sec 6-31N-34E.

Permit given for 330' FN & 1650' FE
same section.

Sentry drilled 1650' FN & 1650' FE
(Presumably)

2/10/83

Memo

From

CARL ULVOG

Chief Geologist

To

I need a telephone number for
Monty Farr (Farr Cattle Co.)

(He ranches in far - Farr? - N.E. New Mex.)

His number used to be 451-7453
or 471 "

I don't know if it was from a N. Mex.
exchange (505); an Okla. exchange (405)
or Colo. exchange (303)

but

nearest towns are
Kenton, Okla. → N.M.
Branson, Colo.
Folsom, N. Mex.

505-471-7453 - no
405- " " - no
303 " " - no

Oil Conservation Division
P.O. Box 2088 Santa Fe, N.M. 87501