

So far as the "capped" well is concerned we are not particularly concerned as it poses no hazard, but the two open holes are a hazard, and should be plugged.

We request and it will be appreciated if you will take immediate action to require Mr. Ringle to comply with the conditions of his Bond.

I shall appreciate hearing from you.

Very truly yours,


GILBERTO ESPINOSA

AGE:ss

Enclosure