

**From:** [Guadalupe Carrasco](#)  
**To:** [Jeffrey Robertson \(jrobertson@blm.gov\)](mailto:jrobertson@blm.gov)  
**Cc:** [Robert McNeill](#); [Bratcher, Mike, EMNRD](#); [Patterson, Heather, EMNRD](#)  
**Subject:** FW: Burch Keely Unit #232 (BKU Satellite E Battery)  
**Date:** Monday, July 07, 2014 3:38:22 PM  
**Attachments:** Work Plan Letter (Amendment).pdf

---

Jeffery,

Attached is a letter describing the delineation you requested below, along with a copy of the site diagram and the analytical results. Please let me know if you have any questions or concerns.

Thanks!

**Lupe Carrasco**

Environmental Coordinator

Concho Resources

Cell: [575.725.0787](tel:575.725.0787)

Office: [575.748.6933](tel:575.748.6933)

[gcarrasco@concho.com](mailto:gcarrasco@concho.com)

[2208 W. Main St.](#)

[Artesia, NM 88210](#)

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

---

**From:** Robertson, Jeffery [<mailto:jrobertson@blm.gov>]  
**Sent:** Friday, May 23, 2014 8:44 AM  
**To:** Guadalupe Carrasco; Mike Bratcher; Robert Grubbs  
**Subject:** Re: Burch Keely Unit #232 (BKU Satellite E Battery)

This well has elevated levels of contaminants that are climbing the deeper the samples go at S1 going from 6700 at 1 foot to 13000 at 4 foot. It shows the same at S5 going from 740 at 4 foot to 1340 at 6 foot. Because of this I researched AFMSS to look at the history of spills on this location and this is the only reported spill. As a result of this information the areas must be fully delineated to obtain the depth that the contaminates clean up to within allowed levels. This is done to record the true depths of all contaminants for this location for the well files history of contaminates. This does not mean that more soil needs to be removed because by doing so would be a hazard to personal but we need to record clean up depths. If required you

may shift the sample points to avoid underground power lines or pipes. If you have any questions feel free to call me anytime.

***Jeffery L. Robertson***

**BLM-CFO**

**Natural Resource Specialist**

Office: 575-234-2230

Cell: 575-361-3568

[jlr Robertson@blm.gov](mailto:jlr Robertson@blm.gov)

On Thu, May 8, 2014 at 1:18 PM, Guadalupe Carrasco <[GCarrasco@concho.com](mailto:GCarrasco@concho.com)> wrote:  
Mr. Robertson,

Attached is a copy of the Work Plan for the Burch Keely Unit #232 (BKU Satellite E Battery) submitted to Mike Bratcher at NMOCD. The Work Plan is in response to the C-141 Initial submitted on March 6, 2014. Please take a look at the attached document and let me know if you have any questions or concerns.

Thanks!

Lupe Carrasco  
Environmental Coordinator  
Concho Resources  
Cell: 575.725.0787  
Office: 575.748.6933  
[gcarrasco@concho.com](mailto:gcarrasco@concho.com)

2208 W. Main St.  
Artesia , NM 88210

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.