

**From:** Patterson, Heather, EMNRD  
**To:** [cbrunson@bbcinternational.com](mailto:cbrunson@bbcinternational.com)  
**Cc:** [Bratcher, Mike, EMNRD](#); [C J Summers](#); [kswinney@bbcinternational.com](mailto:kswinney@bbcinternational.com); ["Kathy Purvis"](#)  
**Subject:** RE: OXY-Corral Draw #2 - Remediation Plan  
**Date:** Thursday, September 18, 2014 9:15:00 AM

---

RE: Oxy \* Corral Draw #2 \* 30-015-21425 \* 2RP-2208

Cliff,

This Remediation Plan is approved as written.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Heather Patterson  
Environmental Specialist  
NMOCD District II  
(575)748-1283 ext.101

---

**From:** Bratcher, Mike, EMNRD  
**Sent:** Tuesday, September 16, 2014 2:04 PM  
**To:** Patterson, Heather, EMNRD  
**Subject:** FW: OXY-Corral Draw #2 - Remediation Plan

---

**From:** Cliff P. Brunson [<mailto:cbrunson@bbcinternational.com>]  
**Sent:** Thursday, August 28, 2014 11:57 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** C J Summers; Ken Swinney; Jennifer Gilkey; Kathy Purvis  
**Subject:** OXY-Corral Draw #2 - Remediation Plan

Mike,

This e-mail is to confirm our conversation on August 11, 2014 about the remediation plan for the above referenced site. I have attached the materials that we used in our discussion. As discussed, Oxy will excavate to a depth of 4 feet across the entire leak area outside of the lined battery. In the areas around SP1, SP2, SB1, SP4, SB3, SP7, and SB2, a liner will be placed in the bottom of the excavations. All of these areas are depicted on the attached site diagram. The liner inside the battery will be cleaned as well. Then the site will then be backfilled with clean soil.

If you would please e-mail your concurrence with this remediation plan, it would be greatly appreciated.

Thanks, Cliff

Cliff P. Brunson, CEI, CRS  
President  
BBC International, Inc.  
World-Wide Environmental Specialists  
Mailing Address:  
P. O. Box 805  
Hobbs, NM 88241-0805 USA  
Shipping Address:  
1324 W. Marland St.  
Hobbs, NM 88240 USA  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
E-Mail: [cbrunson@bbcinternational.com](mailto:cbrunson@bbcinternational.com)

\*\*\*\*\*

Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.

\*\*\*\*\*