From:	Bratcher, Mike, EMNRD
To:	larrym_gdc@hotmail.com
Cc:	Griswold, Jim, EMNRD; Billings, Bradford, EMNRD; Patterson, Heather, EMNRD; Morales, Tony, EMNRD
Subject:	FW: Emailing: KERSEY STATE 001 005.jpg, KERSEY STATE 001 006.jpg, KERSEY STATE 001 007.jpg, KERSEY STATE 001 008.jpg
Date:	Wednesday, April 15, 2015 11:41:31 AM
Attachments:	KERSEY STATE 001 005.jpg KERSEY STATE 001 006.jpg KERSEY STATE 001 007.jpg KERSEY STATE 001 008.jpg

Mr. Marker,

On April 14, 2015, NMOCD personnel performed a routine field inspection on the following well site:

Kersey State 001 * 30-015-05178 * B-16-17s-31e * Eddy County, NM

The attached photos were taken by the OCD field inspector. It was observed that a release of produced fluid, in excess of five bbls, has occurred, allowing fluids to pool inside the unlined, bermed battery area. At this time, OCD requests standing fluid be removed immediately. Saturated soils may be excavated and hauled to an OCD approved disposal facility, as an immediate response action. An Initial Report Form C-141 is to be submitted to the District 2 Office not later than April 29, 2015. The impacted area will require delineation and remediation per NMOCD rules, regulations, and guidelines. A remediation proposal based on delineation results and site ranking, is to be submitted to the District 2 Office for review, not later than May 14, 2015. An attempt was made, unsuccessfully, to contact you at phone numbers OCD has on file. Please update contact information as may be available.

If you have any questions or concerns, please contact me or Heather Patterson in the Artesia (District 2) office.

Mike BratcherHeather PattersonNMOCD District 2575-748-1283 X101811 S. First Streetheather.patterson@state.nm.usArtesia, NM 882100: 575-748-1283 X108C: 575-626-0857F: 575-748-9720F: 575-748-9720mike.bratcher@state.nm.us

-----Original Message-----From: Morales, Tony, EMNRD Sent: Wednesday, April 15, 2015 7:17 AM To: Bratcher, Mike, EMNRD Cc: Dade, Randy, EMNRD; Patterson, Heather, EMNRD; Morales, Tony, EMNRD Subject: Emailing: KERSEY STATE 001 005.jpg, KERSEY STATE 001 006.jpg, KERSEY STATE 001 007.jpg, KERSEY STATE 001 008.jpg

MR. BRATCHER

FYI: KERSEY STATE 001 HOLDING TANK NEXT TO TANK BATTERY. 32.8400014878/103.872653115. HOLDING TANK OVERFLOWED. SPILL CONTAINED INSIDE CONTAINMENT BURM.

Tony Morales, Compliance Officer EMNRD-OCD 811 S. First St. Artesia, NM 88210 575-748-1283 ext. 106 575-703-0233 (cellular) Tony.Morales@state.nm.us

Your message is ready to be sent with the following file or link attachments:

KERSEY STATE 001 005.jpg KERSEY STATE 001 006.jpg KERSEY STATE 001 007.jpg KERSEY STATE 001 008.jpg

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.