## **Bratcher, Mike, EMNRD**

**From:** Gregston, Terry G <tgregsto@blm.gov> **Sent:** Friday, January 25, 2013 12:37 PM

**To:** dfrick@linnenergy.com; rragland@linnenergy.com; jhernandez@linnenergy.com;

gawink@linnenergy.com; Bratcher, Mike, EMNRD; tbutters@linnenergy.com;

cgolding@linnenergy.com

**Cc:** brian.weaver@skaconsulting.com; tbarrett@swca.com; Stein, Chris M

**Subject:** jpg of treatment boundary and spills

**Attachments:** Turner B South Premier Archeological Treatment Plan Boundary-012513.jpg

For those of you who do not have ArcMap, here is a jpg of the Turner B South Premier spills and the Arch treatment boundary laid atop an aerial photo.

## **Terry Gregston**

Environmental Protection Specialist Bureau of Land Management 620 E. Greene St. Carlsbad, NM 88220 Office (575) 234-5958 Cell (575) 361-2635 Fax (575) 234-5927

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.