

**From:** [Tucker, Shelly](#)  
**To:** [Heather Dolphin](#)  
**Cc:** [Art Arias \(aaarias@blm.gov\)](#); [Bratcher, Mike, EMNRD](#); [Patterson, Heather, EMNRD](#)  
**Subject:** Re: Memorial\_NSLU #3 Injection Line\_50bbbls PW\_10-12-15  
**Date:** Thursday, October 15, 2015 10:04:48 AM

---

Please submit a work plan detailing intentions. You will also need to make sure this area is cleared for Arch prior to any excavation activities.

The BLM approval/acceptance does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

*Shelly J Tucker*

Environmental Protection Specialist  
Bureau of Land Management

620 E. Greene St  
Carlsbad, NM 88220

575.234.5905 - Direct  
575.361.0084 - Cellular

[stucker@blm.gov](mailto:stucker@blm.gov)



On Wed, Oct 14, 2015 at 4:19 PM, Heather Dolphin <[heather.dolphin@memorialrd.com](mailto:heather.dolphin@memorialrd.com)> wrote:

Please find attached the C-141 for the below reported spill.

---

**From:** Heather Dolphin  
**Sent:** Monday, October 12, 2015 4:53 PM  
**To:** Art Arias ([aaarias@blm.gov](mailto:aaarias@blm.gov)) <[aaarias@blm.gov](mailto:aaarias@blm.gov)>; Heather Dolphin <[heather.dolphin@memorialrd.com](mailto:heather.dolphin@memorialrd.com)>; Mike Bratcher ([mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)) <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Tucker, Shelly <[stucker@blm.gov](mailto:stucker@blm.gov)>

**Subject:** Memorial\_NSLU #3 Injection Line\_50bbbls PW\_10-12-15

North Square Lake Unit #003

30-015-20183

Memorial had a hole in the injection line at NSLU #3, initial report is 50bbbls PW 25' x 20' off location, no fluid recovered. I will follow-up with a C-141 when I get more details.

Thank You

**Heather Dolphin**

Sr. Regulatory Specialist  
Memorial Resource Development Corp.  
500 Dallas Street, Suite 1800  
Houston , TX 77002  
Direct (832) 408-8603  
Mobile (832)-797-1334  
Main (713) 588-8300  
Fax (713) 588-8301  
[heather.dolphin@memorialrd.com](mailto:heather.dolphin@memorialrd.com)

[Click here for Memorial Resource Development's Electronic Mail Disclaimer](#)