

**From:** [Billings, Bradford, EMNRD](#)  
**To:** [wayne price](#)  
**Cc:** [Griswold, Jim, EMNRD](#); [Bratcher, Mike, EMNRD](#); [Patterson, Heather, EMNRD](#)  
**Subject:** RE: BKE-Data/Plan  
**Date:** Monday, August 24, 2015 2:00:31 PM

---

Hi Wayne,

It has been a bit, so checking in on Key-BKE SWD. Have you received any of the MRO data, or the data from whatever samples Key collected for themselves? What is next in the loop for the site? Thanks a bunch and hope all is well with you.

Brad

-----Original Message-----

From: wayne price [<mailto:wayneprice77@earthlink.net>]  
Sent: Monday, August 03, 2015 6:47 PM  
To: Bobby Sisson; Desiree Crenshaw  
Cc: Brad Stauffer; Maren Coligan; Daniel Bach; Griswold, Jim, EMNRD; Billings, Bradford, EMNRD; waprice23@hotmail.com  
Subject: BKE-additional sampling recommended by OCD 2R-2618 Aug 03, 2015

TO Bobby Sessions:

Today I had an opportunity to discuss a path forward for the BKE site with OCD, and they made a recommendation to collect a minimum of 5 grab samples in the floor of the excavated area and to grab 3 sidewall samples on each long side and 2 sidewall samples on short sides.

Today we did that, except we actually collected 7 floor samples and a total of 10 sidewall samples. We will run BTEX, TPH (GRO-DR0-MRO), and Chlorides.

We did receive a small rainfall and the bottom was damp and it appeared there was some noticeable salt leaching to the surface. My observations of the floor soils fairly well matches the soil type noticed in the field background samples, which does consist of probably 20% clay contained in these soils. There was no visual free oil stains or odors observed today.

We also logged the GPS locations and took photos of the samples collected today in reference to the floor exploratory holes collected July 22, 2015.

Wayne Price-Price LLC